

April 6, 1973

Docket No. 50-249

Mr. Harold G. Mangelsdorf
Chairman, Advisory Committee
on Reactor Safeguards
U. S. Atomic Energy Commission
Washington, D. C. 20545

Dear Mr. Mangelsdorf:


Sixteen (16) copies of the following are transmitted for the
Committee's information:

TWX from Commonwealth Edison Company dated March 26, 1973,
reporting that the Dresden 3 main steam line area tempera-
ture switches were out of calibration.

Letter from Commonwealth Edison Company dated March 26,
1973, reporting that 13 of the 16 Dresden 3 high pressure
coolant injection area temperature sensors were found to
operate above the Technical Specifications limit.

Letter from Commonwealth Edison Company dated March 30,
1973, reporting that a Barton differential pressure
switch on the low pressure coolant injection system
loop selection logic was found damaged at Dresden 3.

Sincerely,



Donald J. Skovholt
Assistant Director for
Operating Reactors
Directorate of Licensing

Distribution
Docket File
Branch Reading

Enclosures:
As stated

OFFICE ▶	L:ORB #2								
SURNAME ▶	RMDiggs								
DATE ▶	4/6/73								