

March 5, 1973

Docket No. 50-249

Mr. Harold G. Mangelsdorf
Chairman, Advisory Committee
on Reactor Safeguards
U. S. Atomic Energy Commission
Washington, D. C. 20545


Dear Mr. Mangelsdorf:

Sixteen (16) copies of the following are transmitted for the
Committee's information:

Letter from Commonwealth Edison Company dated February 23,
1973, reporting that during local leak rate testing of the
rubber seated torus vent relief valves at Dresden Unit 3,
two check valves were found to be leaking excessively.

Sincerely,

Distribution
Docket File
Branch Reading


Donald J. Skovholt
Assistant Director for
Operating Reactors
Directorate of Licensing

Enclosures:
As stated

OFFICE ▶	L: ORB #2					
SURNAME ▶	RMDiggs: sjh					
DATE ▶	3/5/73					