

January 17, 1973

Docket No. 50-249

Dr. Chester P. Siess
Chairman, Advisory Committee
on Reactor Safeguards
U. S. Atomic Energy Commission
Washington, D. C. 20545

Dear Dr. Siess:

Sixteen (16) copies of the following are transmitted for the
Committee's information:

TWX from Commonwealth Edison Company dated January 10,
1973, reporting that a level switch on the Dresden
Unit 3 LPCI system was out of calibration.

TWX from Commonwealth Edison Company dated January 9,
1973, reporting that the Dresden Unit 3 HPCI high
steam flow isolation sensors were out of calibration.

Sincerely,

Distribution
Docket File
Branch Reading

Donald J. Skovholt
Donald J. Skovholt
Assistant Director for
Operating Reactors
Directorate of Licensing

Enclosures:
As stated

OFFICE ▶	L:ORB #2				
SURNAME ▶	RMDiggs:sih				
DATE ▶	1/17/73				

W