

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 8708200374 DOC. DATE: 87/08/17 NOTARIZED: NO
 FACIL: 50-335 St. Lucie Plant, Unit 1, Florida Power & Light Co.
 50-389 St. Lucie Plant, Unit 2, Florida Power & Light Co.

DOCKET #
 05000335
 05000389

AUTH. NAME: WOODY, C. D.
 RECIP. NAME: AUTHOR AFFILIATION: Florida Power & Light Co.
 RECIPIENT AFFILIATION: Document Control Branch (Document Control Desk)


SUBJECT: Responds to violations noted in Insp Repts 50-335/87-11 & 50-389/87-10. Corrective actions: temporary changes to Operating Procedures 1-0530020 & 1-0530021 implemented & will remain in effect until procedures revised.

DISTRIBUTION CODE: IE06D COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 2
 TITLE: Environ & Radiological (50 DKT)-Insp Rept/Notice of Violation Respons

NOTES:

	RECIPIENT ID CODE/NAME	COPIES		RECIPIENT ID CODE/NAME	COPIES	
		LTR	ENCL		LTR	ENCL
	PD2-2 LA	1	0	PD2-2 PD	1	1
	TOURIGNY, E	1	1			
INTERNAL:	AEOD/DQA	1	1	AEOD/DSP	1	1
	NMSS/SGOB	1	1	NRR/DOEA/EAB	1	1
	NRR/DREP/EPB	1	1	NRR/DREP/RPB	2	2
	NRR/PMAS/ILRB	1	1	OGC/HDS2	1	1
	REG ETL 02	1	1	RES	1	1
	RES DEPY GI	1	1	RGN2 FILE 01	1	1
	RGN2/DRSS/EPRPB	1	1	RGN4 MURRAY, B	1	1
EXTERNAL:	LPDR	1	1	NRC PDR	1	1
	NSIC	1	1			

TOTAL NUMBER OF COPIES REQUIRED: LTR 21 ENCL 20



AUGUST 17 1987

L-87-343
10 CFR 2.201

U. S. Nuclear Regulatory Commission
Attn: Document Control Desk
Washington, D. C. 20555

Gentlemen:

Re: St. Lucie Units 1 and 2
Docket Nos. 50-335 and 50-389
Inspection Report 335/87-11 and 389/87-10

Florida Power & Light Company has reviewed the subject inspection report, and pursuant to the provisions of 10 CFR 2.201 the response is attached.

There is no proprietary information in this report.

Very truly yours,

C. O. Woody
Group Vice President
Nuclear Energy

COW/GRM/gp

Attachment

cc: Dr. J. Nelson Grace, Regional Administrator, Region II, USNRC
Senior Resident Inspector, USNRC, St. Lucie Plant

8708200374 870817
PDR ADDCK 05000335
Q PDR

IEOC
11

Re: St. Lucie Units 1 and 2
Docket Nos. 50-335 and 50-389
Inspection Report 335/87-11 and 389/87-10

VIOLATION

During the Nuclear Regulatory Commission (NRC) inspection conducted on June 22-26, 1987, a violation of NRC requirements was identified. The violation involved inadequate procedures. In accordance with the "General Statement of Policy and Procedure for NRC Enforcement Actions," 10 CFR Part 2, Appendix C (1986), the violation is listed below:

Unit 1 Technical Specification (TS) 6.8.1.a, requires that written procedures be established, implemented, and maintained for activities recommended in Appendix A of Regulatory Guide 1.33, Revision 2, February 1978.

Appendix A of Regulatory Guide 1.33, Revision 2, February 1978, states that the following is a typical safety-related activity that should be covered by written procedures: PWR Gaseous Effluent System-Collection, Storage, and Discharge.

Contrary to the above, Operating Procedure (OP) 1-530020, Revision 8, July 15, 1985, Waste Gas System Operation and 1-0530021, Revision 30, January 28, 1987, controlled Gaseous Batch Release to Atmosphere, were inadequate in that the details for the Unit 1 waste gas system operation and for the waste gas system lineup were not included in the procedures to reflect the current mode of operation

RESPONSE

1. Florida Power & Light Company (FPL) concurs with the violation.
2. Through personnel oversight, the Unit 1 operating procedures were not updated as required to be consistent with the current mode of operation.
3. Temporary changes to Operating Procedures 1-0530020 and 1-0530021 have been implemented and will remain in effect until the procedures are revised to reflect the current method of operation.
4. Responsible plant personnel have been made aware of this violation and the need to address all aspects of changes in operating methodology. FPL believes that this action is sufficient to prevent recurrence.
5. The procedure revisions are expected to be issued by August 31, 1987.

