

# ACCELERATED DISTRIBUTION DEMONSTRATION SYSTEM

## REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 8909070287      DOC. DATE: 89/08/23      NOTARIZED: NO      DOCKET #  
 FACIL: 50-335 St. Lucie Plant, Unit 1, Florida Power & Light Co.      05000335  
       50-389 St. Lucie Plant, Unit 2, Florida Power & Light Co.      05000389

AUTH. NAME      AUTHOR AFFILIATION  
 EBNETER, S.D.      Region 2, Ofc of the Director  
 RECIP. NAME      RECIPIENT AFFILIATION  
 WOODY, C.O.      Florida Power & Light Co.

SUBJECT: Confirms 890814 telcon between G Madden & RV Crlenjak re enforcement conference scheduled for 890905.

DISTRIBUTION CODE: IE01D      COPIES RECEIVED: LTR 1 ENCL 1      SIZE: 1  
 TITLE: General (50 Dkt)-Insp Rept/Notice of Violation Response

NOTES:

	RECIPIENT ID CODE/NAME	COPIES LTR ENCL	RECIPIENT ID CODE/NAME	COPIES LTR ENCL
	PD2-2 PD	1 1	NORRIS, J	1 1
INTERNAL:	ACRS	2 2	AEOD	1 1
	AEOD/DEIIB	1 1	AEOD/TPAD	1 1
	DEDRO	1 1	LOIS, ERASMIA	1 1
	NRR SHANKMAN, S	1 1	NRR/DEST. DIR	1 1
	NRR/DLPQ/PEB	1 1	NRR/DOEA DIR 11	1 1
	NRR/DREP/EPB 10	1 1	NRR/DREP/RPB 10	2 2
	NRR/PMAS/ILRB12	1 1	NUDOCS-ABSTRACT	1 1
	OE LIEBERMAN, J	1 1	OGC/HDS2	1 1
	REG. FILE 02	1 1	RES MORISSEAU, D	1 1
	RGN2 FILE 01	1 1		
EXTERNAL:	LPDR	1 1	NRC PDR	1 1
	NSIC	1 1		

TOTAL NUMBER OF COPIES REQUIRED: LTR 26 ENCL 26

R  
I  
D  
S  
/  
A  
D  
D  
S

*Official*

AUG 23 1989

Docket Nos. 50-335, 50-389  
License Nos. DPR-67, NPF-16

Florida Power and Light Company  
ATTN: Mr. C. O. Woody, Acting  
Senior Vice President - Nuclear  
P. O. Box 14000  
Juno Beach, FL 33408-0420

Gentlemen:

SUBJECT: ENFORCEMENT CONFERENCE - ST. LUCIE DOCKET NOS. 50-335 AND 50-389

This confirms the telephone conversation between Mr. G. Madden of your staff and Mr. R. V. Crlenjak of my staff on August 14, 1989, concerning an enforcement conference to be conducted at the Region II Office, 26th floor conference room, on September 5, 1989, at 10:00 a.m. The purpose of this meeting is to discuss 1) inoperable EDG 1B fuel transfer system; 2) temporary filter media installed on containment cooler during power operations; and 3) containment cooler access doors not properly sealed as required by the mode of operation, as delineated in our Inspection Report No. 50-335,389/89-20.

Should you have any questions regarding these arrangements, we will be pleased to discuss them.

Sincerely,

Original signed by

Stewart D. Ebnetter  
Regional Administrator

cc: D. A. Sager, Vice President  
St. Lucie Nuclear Plant  
G. J. Boissy, Plant Manager  
J. B. Harper, QA Superintendent  
State of Florida

bcc: NRC Resident Inspector  
Document Control Desk  
NRC Section Chief  
NRC Project Engineer

8909070287 890823  
PDR ADOCK 05000335  
Q PIC

RII:DRP  
*SVias*  
SVias  
08/24/89

RII:DRP  
*SVias*  
for R Crlenjak  
08/24/89

RII:DRP  
*MSinkoTe*  
MSinkoTe  
08/24/89

RII:DRP  
*LReyes*  
LReyes  
08/23/89

RII:DRP  
*GJenkins*  
GJenkins  
08/23/89

RII:RA  
*BGrimes*  
BGrimes  
08/23/89

11  
JEO1