

ACCELERATED DISTRIBUTION DEMONSTRATION SYSTEM

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 9001180356 DOC. DATE: 90/01/11 NOTARIZED: NO DOCKET #
 FACIL: 50-389 St. Lucie Plant, Unit 2, Florida Power & Light Co. 05000389
 AUTH. NAME AUTHOR AFFILIATION
 GOLDBERG, J.H. Florida Power & Light Co.
 RECIP. NAME RECIPIENT AFFILIATION
 Document Control Branch (Document Control Desk)

SUBJECT: Informs that no check valves subj to NRC Bulletin 89-002, "Stress Corrosion Cracking..." installed at facility.

DISTRIBUTION CODE: IE32D COPIES RECEIVED: LTR 1 ENCL 0 SIZE: 2
 TITLE: Bulletin Response 89-02 re Cracking of High-Hardness Type 410 Bolting

NOTES:

	RECIPIENT		COPIES			RECIPIENT		COPIES	
	ID	CODE/NAME	LTTR	ENCL		ID	CODE/NAME	LTTR	ENCL
	PD2-2	LA	1	0		PD2-2	PD	1	1
		NORRIS, J	1	1					
INTERNAL:	AEOD/DOA		1	1	AEOD/DSP/TPAB			1	1
	NRR/DET/ECMB9H		2	2	NRR/DET/EMEB9H3			1	1
	NRR/DOEA/OEAB11		1	1	NRR/DOEA/OGCB11			1	1
	NRR/DREP/PEPB9D		1	1	NRR/DST 8E2			1	1
	NRR/HERMAN /B		1	1	NRR/MCLELLAN, T			1	1
	NRR/PMAS/ILRB12		1	1	NRR/ROOD, H			1	1
	NRR/SELLERS, D.		1	1	NUDOCS-ABSTRACT			1	1
	REG-FILE-02		1	1	RES/DSIR/EIB			1	1
	RGN2	FILE 01	1	1					
EXTERNAL:	LPDR		1	1	NRC PDR			1	1
	NSIC		1	1					

NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK, ROOM P1-37 (EXT. 20079) TO ELIMINATE YOUR NAME FROM DISTRIBUTION LISTS FOR DOCUMENTS YOU DON'T NEED!

TOTAL NUMBER OF COPIES REQUIRED: LTTR 24 ENCL 23

A/0-1



JANUARY 11 1990

L-90-04
10 CFR 50.54(f)

U. S. Nuclear Regulatory Commission
Attn: Document Control Desk
Washington, D. C. 20555

Gentlemen:

Re: St. Lucie Unit 2
Docket No. 50-389
NRC Bulletin No. 89-02

On July 19, 1989, the NRC issued NRC Bulletin No. 89-02, "Stress Corrosion Cracking Of High-Hardness Type 410 Stainless Steel Internal Preloaded Bolting In Anchor Darling Model S350W Swing Check Valves Or Valves Of Similar Design". The NRC requested that licensees identify, disassemble and inspect certain types of swing check valves which may contain Type 410 stainless steel (SS) bolting material. Licensees who do not identify Anchor Darling Model S350W swing check valves with Type 410 SS bolts subject to this bulletin and do not have valves of similar design with preloaded Type 410 SS bolt material were requested to submit to the NRC a letter of confirmation of these facts by January 17, 1990.

No check valves subject to NRC Bulletin No. 89-02 are installed at St. Lucie Unit 2. Therefore, no actions are required regarding inspection and/or bolting replacement.

Should there be any further questions, please contact us.

Very truly yours,

J. H. Goldberg
Executive Vice President

JHG/EJW/gp

cc: Stewart D. Ebnetter, Regional Administrator, Region II, USNRC
Senior Resident Inspector, USNRC, St. Lucie Plant

9001180356 900111
PDR ADOCK 05000389
Q PDC

STATE OF FLORIDA)
)
COUNTY OF PALM BEACH) ss.

J. H. Goldberg being first duly sworn, deposes and says:

That he is an Executive Vice President, of Florida Power and Light Company, the Licensee herein;

That he has executed the foregoing document; that the statements made in this document are true and correct to the best of his knowledge, information and belief, and that he is authorized to execute the document on behalf of said Licensee.

J. H. Goldberg
J. H. Goldberg

Subscribed and sworn to before me this
11 day of January, 1990.

Robert J. Economy

NOTARY PUBLIC, in and for the County of
Palm Beach, State of Florida

Notary Public, State of Florida
My Commission Expires June 1, 1993
Bonded Thru Troy Fain - Insurance Inc.

My Commission expires _____