

ACCELERATED DISTRIBUTION DEMONSTRATION SYSTEM

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 9110100187 DOC. DATE: 91/10/02 NOTARIZED: NO DOCKET #
 FACIL: 50-335 St. Lucie Plant, Unit 1, Florida Power & Light Co. 05000335
 50-389 St. Lucie Plant, Unit 2, Florida Power & Light Co. 05000389
 AUTH. NAME AUTHOR AFFILIATION
 SAGER, D.A. Florida Power & Light Co.
 RECIP. NAME RECIPIENT AFFILIATION
 Document Control Branch (Document Control Desk)

SUBJECT: Suppls 890403 & 900508 responses to NRC Bulletin 88-010, "Nonconforming Molded-Case Circuit Breakers." Two remaining circuit breakers, identified in 910508, 1tr will be replaced by Nov 1991.

DISTRIBUTION CODE: IE21D COPIES RECEIVED: LTR 1 ENCL 0 SIZE: 1
 TITLE: Bulletin Response 88-10 - Nonconforming Molded Case Circuit Breakers.

NOTES:

	RECIPIENT		COPIES			RECIPIENT		COPIES	
	ID	CODE/NAME	LTTR	ENCL		ID	CODE/NAME	LTTR	ENCL
	PD2-2	LA	1	0		PD2-2	PD	1	1
	NORRIS,	J	1	1					
INTERNAL:	AEOD/DOA		1	1	AEOD/DSP/TPAB			1	1
	NRR DOEA/GCB	11	1	1	NRR GILL, A.S.			1	1
	NRR STONE, J.C.		1	1	NRR/DET/EMEB 7E			1	1
	NRR/DOEA/OEAB11		1	1	NRR/DOEA/OGCB11			1	1
	NRR/DREP/PEPB9D		1	1	NRR/DST 8E2			1	1
	NRR/PWAS/ILRB12		1	1	NRR/POTAPOVS, U			1	1
	REG FILE	02	1	1	RES/DSIR/EIB			1	1
	RGN2	FILE 01	1	1					
EXTERNAL:	NRC	PDR	1	1	NSIC			1	1

NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK, ROOM P1-37 (EXT. 20079) TO ELIMINATE YOUR NAME FROM DISTRIBUTION LISTS FOR DOCUMENTS YOU DON'T NEED!

TOTAL NUMBER OF COPIES REQUIRED: LTTR 20 ENCL ~~19~~ 0

R
I
D
S
/
A
D
D
S

R
I
D
S
/
A
D
D
S



October 2, 1991

L-91-262
10 CFR 50.4

U. S. Nuclear Regulatory Commission
Attn: Document Control Desk
Washington, D. C. 20555

Gentlemen:

RE: St. Lucie Units Nos. 1 and 2
Docket Nos. 50-335 and 50-389
NRC Bulletin 88-10 Closure

By letter L-89-120 dated April 3, 1989 and L-90-161 dated May 8, 1990, Florida Power and Light Company (FPL) responded to NRC Bulletin 88-10 "Non conforming Molded-Case Circuit Breakers" for St. Lucie Units 1 and 2. In the responses, FPL confirmed that activities required to address the issue of substandard molded-case circuit breakers had been or would be performed by the fall of 1990.

The two remaining circuit breakers (items nos. 4 and 5) identified in attachment 1 of FPL letter L-90-161 were replaced by November 1990. This letter provides confirmation that FPL has completed all the actions identified in the responses to the subject bulletin.

Please contact us if there are any questions about this submittal.

Very truly yours,

D.A. Sager
H.J. Boinsky
D. A. Sager
Vice President
St. Lucie Plant

By

DAS/GRM/kw

cc: Stewart D. Ebnetter, Regional Administrator, Region II, USNRC
Senior Resident Inspector, USNRC, St. Lucie Plant

DAS/PSL #530-91

9110100187 911002
FDR ADOCK 05000335
Q PIR

JE21