



UNITED STATES  
NUCLEAR REGULATORY COMMISSION  
REGION III  
2443 WARRENVILLE ROAD, SUITE 210  
LISLE, ILLINOIS 60532-4352

AUG 08 2017

Thomas J. Moenster  
Radiation Safety Officer  
Missouri Baptist Medical Center  
3015 N. Ballas Road  
St. Louis, MO 63131

Dear Mr. Moenster:

Enclosed is Amendment No. 88 to your NRC Material License No. 24-11128-02 in accordance with your request.

Please review the enclosed document carefully and be sure that you understand all conditions. If there are any errors or questions, please notify the U.S. Nuclear Regulatory Commission, Region III office at (630) 829-9887 so that we can provide appropriate corrections and answers.

In correspondence dated January 12, 2017; February 9, 2017; March 6, 2017; March 31, 2017; April 7, 2017; and May 12, 2017, you provided closeout/decommissioning surveys for Building C, 3009 N. Ballas Road, Suite 262, St. Louis, Missouri; MB Cardiology Outpatients, 3315 N. Ballas Road, Suite 262C, St. Louis, Missouri; and Building D, 3023 N. Ballas Road, Suite 150, St. Louis, Missouri. Other areas of use specified in your correspondence were added and/or deleted and/or modified in the course of remodeling work done at the licensed locations of use. The sites listed above were requested to be released for unrestricted use.

The NRC staff has reviewed your final status surveys. Based on its review, the staff has concluded that all licensable radioactive material has been removed from the facilities at the locations of use noted above; and/or the areas of use qualified for "notification" under 10 CFR 35.13(e) and 35.14(b)(5), and residual radioactive material attributable to licensed activities does not exceed current NRC criteria. Based on these conclusions no further remediation or actions with respect to NRC regulated material is required for this location and it is suitable for unrestricted use.

Regarding the location of use you requested to be deleted from your license, because it had not actually been a location of use and was never used for radioactive materials work, at MB Cardiology Outpatients, 3315 N. Ballas Road, Suite 262C, St. Louis, Missouri, we noted that this address was added to your license about 6 years ago. It was included in amendments, a renewal of this license, and inspections conducted by NRC without being identified as an erroneous site.

If this address was not used for licensed purposes, was it accidentally requested to be added to the license instead of a different address of use where licensed materials were used but the address was not added to the license by mistake? If this situation occurred, please contact me immediately at 630-829-9841.

The enclosed document contains sensitive security-related information.  
When separated from this cover letter this letter is uncontrolled.

T. Moenster

- 2 -

**This amendment incorporates many areas of use and address/location of use changes, and some corresponding changes in authorized activities. Please examine your license carefully to ensure it is correct and that you understand all authorizations and conditions.**

**If you have any questions concerning this amendment please contact me at either (630) 829-9841 or (800) 522-3025, ext. 9841. My fax number is 630-515-1078. My email address is colleen.casey@nrc.gov.**

NRC's Regulatory Issue Summary (RIS) 2005-31 provides criteria to identify security-related sensitive information and guidance for handling and marking of such documents. This ensures that potentially sensitive information is not made publicly available through ADAMS, the NRC's electronic document system.

Pursuant to NRC's RIS 2005-31 and in accordance with 10 CFR 2.390, the enclosed license document is exempt from public disclosure because its disclosure to unauthorized individuals could present a security vulnerability.

The RIS may be located on the NRC Web site at: <http://www.nrc.gov/reading-rm/doc-collections/gen-comm/reg-issues/2005/ri200531.pdf> and the link for frequently asked questions regarding protection of security related sensitive information may be located at: <http://www.nrc.gov/reading-rm/sensitive-info/faq.html>.

A copy of this letter will be available electronically for public inspection in the NRC Public Document Room or from the Publicly Available Records (PARS) component of NRC's document system (ADAMS).

The NRC's document system is accessible from the NRC Web site at <http://www.nrc.gov/reading-rm/adams.html> (the Public Electronic Reading Room).

You will be periodically inspected by NRC.

Failure to conduct your program in accordance with NRC regulations, license conditions, and representations made in your license application and supplemental correspondence with NRC will result in enforcement action against you.

This could include issuance of a notice of violation, or imposition of a civil penalty, or an order suspending, modifying or revoking your license as specified in the General Statement of Policy and Procedure for NRC Enforcement Actions.

Since serious consequences to employees and the public can result from failure to comply with NRC requirements, prompt and vigorous enforcement action will be taken when dealing with licensees who do not achieve the necessary meticulous attention to detail and the high standard of compliance which NRC expects of its licensees.

The NRC's Safety Culture Policy Statement became effective in June 2011.

While a policy statement and not a regulation, it sets forth the agency's *expectations* for individuals and organizations to establish and maintain a positive safety culture.

T. Moenster


- 3 -

You can access the policy statement and supporting material that may benefit your organization on NRC's safety culture Web site at:

<http://www.nrc.gov/about-nrc/regulatory/enforcement/safety-culture.html>.

We strongly encourage you to review this material and adapt it to your particular needs in order to develop and maintain a positive safety culture as you engage in NRC-regulated activities.

Sincerely,



Colleen Carol Casey  
Materials Licensing Branch

License No. 24-11128-02

Docket No. 030-08325

Enclosure:

Amendment No. 88