

ACCELERATED DOCUMENT DISTRIBUTION SYSTEM

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 9309170226 DOC. DATE: 93/09/17 NOTARIZED: NO DOCKET #
 FACIL: 50-335 St. Lucie Plant, Unit 1, Florida Power & Light Co. 05000335
 AUTH. NAME AUTHOR AFFILIATION
 SAGER, D.A. Florida Power & Light Co.
 RECIPIENT NAME RECIPIENT AFFILIATION
 Document Control Branch (Document Control Desk)

See Report

SUBJECT: Forwards Rev 0 of "Second ISI Interval Second Insp Period Second Outage 1993 Summary Rept Submittal." Rept provides info required to be included in SG tube ISI special rept.

DISTRIBUTION CODE: A047D COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 2+200
 TITLE: OR Submittal: Inservice/Testing/Relief from ASME Code

NOTES:

	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL
	PD2-2 LA	1 0	PD2-2 PD	1 1
	NORRIS, J	2 2		
INTERNAL:	ACRS	6 6	AEOD/DSP/ROAB	1 1
	NRR/DE/EMEB	1 1	NRR/EMCB	1 1
	NUDOCS-ABSTRACT	1 1	OC/LFDGB	1 0
	OGC/HDS3	1 0	<u>REG FILE</u> 01	1 1
	RES/DSIR/EIB	1 1		
EXTERNAL:	EG&G BROWN, B	1 1	EG&G RANSOME, C	1 1
	NRC PDR	1 1	NSIC	1 1

NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK, ROOM P1-37 (EXT. 504-2065) TO ELIMINATE YOUR NAME FROM DISTRIBUTION LISTS FOR DOCUMENTS YOU DON'T NEED!

TOTAL NUMBER OF COPIES REQUIRED: LTTR 22 ENCL 19

R
I
D
S
/
A
D
D
S
/
A
D
D
S

MA-2
dbp



P.O. Box 128, Ft. Pierce, FL 34954-0128

L-93-237
10 CFR 50.55a
10 CFR 50.36

September 17, 1993

U. S. Nuclear Regulatory Commission
Attn: Document Control Desk
Washington, DC 20555

Re: St. Lucie Unit 1
Docket No. 50-335
1993 Spring Refueling Outage
Inservice Inspection Reports

Enclosed are the ASME Section XI Inservice Inspection Reports for St. Lucie Unit 1 1993 spring refueling outage. Enclosure 1 is the NIS-1 Inservice Inspection Reports. Enclosure 2 is the NIS-2 Owner's Reports of Repairs and Replacements. The Forms NIS-1 and NIS-2 Inservice Inspection Summary Reports are required by ASME Code Section XI. The reports are to be submitted within 90 days of completing the refueling outage inservice inspection.

This report provides the information required to be included in the Steam Generator Tube Inservice Inspection Special Report. The report is being included pursuant to sections 4.4.5.5.b and 6.9.2 of the St. Lucie Unit 1 Technical Specifications.

Should there be any questions, please contact us.

Very truly yours,

D.A. SAGER
By H.F. Baisy
D. A. Sager
Vice President
St. Lucie Plant

DAS/CDW/kw

Enclosures

cc: Stewart D. Ebnetter, Regional Administrator, Region II, USNRC
Senior Resident Inspector, USNRC, St. Lucie Plant

DAS/PSL#990-93

9309170226 930917
PDR ADDCK 05000335
PDR

ADH-7

170001

Re: St. Lucie Unit 1
Docket No. 50-335
1993 Spring Refueling Outage
Inservice Inspection Reports

ENCLOSURE 1

NIS-1 Inservice Inspection Reports