



November 27, 1998

L-98-296
10 CFR 50.36
10 CFR 50.4

U.S. Nuclear Regulatory Commission
Attn: Document Control Desk
Washington, DC 20555

Re: St. Lucie Unit 2
Docket No. 50-389
Special Report
Steam Generator Tube Plugging Report

This letter is being sent pursuant to St. Lucie Unit 2 Technical Specification 4.4.5.5.a. The following number of tubes were plugged during the Unit 2 refueling outage (SL2-11):

Steam Generator 2A - 12
Steam Generator 2B - 11

Cumulative tubes plugged during this outage and previous outages:

Steam Generator 2A - 319
Steam Generator 2B - 279

Should you have any questions on this information, please contact us.

Very truly yours,

J. A. Stall
Vice President
St. Lucie Plant

JAS/GRM

cc: Regional Administrator, Region II, USNRC
Senior Resident Inspector, USNRC, St. Lucie Plant

9812040053 981127
PDR ADOCK 05000389
P PDR

1/0

0001