

~~OFFICIAL USE ONLY - SECURITY RELATED INFORMATION~~

July 20, 2017

U.S. Nuclear Regulatory Commission
ATTN: Document Control Desk
Washington, DC 20555-0001

This letter is in response to Notice of Violation Docket No. 030-37816, License No. 17-29308-01.

Subject: Incomplete survey records and calculation errors.

The radiographer failed to complete a survey, particularly the area boundaries and posting. In review of the 8 days this radiographer worked in April 2017, the radiographer had completed the remainder of his survey sheets in meticulous detail. Why he skipped/missed completing a survey is hard to understand.

We have had a discussion with the radiographer about completeness and correctness of information. The radiographer and the direct managers will review all documentation, paying more attention to detail. We will perform an in-house audit and check for compliance within 45 days.

Subject: Errors in calculations

The radiographer made some errors when making the boundary calculations. However, the documented boundary distances and mR values recorded are correct for the source strength and distances recorded on his survey sheet. We are working with the radiographer to correct the way his calculations are performed going forward.

Regards,



Russell Alan Phillips
Corporate Assistant RSO/NRC License RSO

~~OFFICIAL USE ONLY - SECURITY RELATED INFORMATION~~

IED7
RGN-TV

