

50-237
50-249


Regulatory Cy.



Commonwealth Edison Company

ONE FIRST NATIONAL PLAZA ★ CHICAGO, ILLINOIS

Address Reply to:
POST OFFICE BOX 767 ★ CHICAGO, ILLINOIS 60690



July 20, 1971

Dr. Peter A. Morris, Director
Division of Reactor Licensing
U.S. Atomic Energy Commission
Washington, D.C. 20545

Subject: Additional Information concerning Special Report No. 15, Dresden Unit 3, DPR-25 and Special Report No. 3, Dresden Unit 2, DPR-19

Dear Dr. Morris:

In a letter dated March 22, 1971, we submitted to you Special Report No. 3 "Investigation of Failure of Radioactive Liquid Waste System." Following a review of this report, members of your staff requested an updated Process Flow Diagram of the liquid radwaste system. Enclosed is the requested diagram.

In a letter dated June 28, 1971, we submitted to you Special Report No. 15 "Jet Pump Flow Blockage of the Dresden 3 Reactor March 15, 1971." Following a review of this report by members of your staff, additional information was requested concerning the magnitude of release rates if fuel damage were to occur due to missing hardware from a purge dam. Enclosed is the supplementary information which you requested.


In addition to three signed originals, 19 copies of this information are also submitted.

Very truly yours,

Byron Lee, Jr.
Byron Lee, Jr.
Assistant to the President

SUBSCRIBED and SWORN to
before me this 20th day
of July, 1971.

Patricia A. Nelson
Notary Public



3280

LB