



Regulatory

File Cy:

# Commonwealth Edison Company

ONE FIRST NATIONAL PLAZA ★ CHICAGO, ILLINOIS

Address Reply to:

POST OFFICE BOX 767 ★ CHICAGO, ILLINOIS 60690

August 18, 1972



Mr. Angelo Giambusso  
Deputy Director for Reactor Projects  
Directorate of Licensing  
U.S. Atomic Energy Commission  
Washington, D.C. 20545

Subject: Corrections to Special Report No. 16  
"Fuel Inspection and Evaluation" -  
Dresden Unit 3 - AEC Dkt 50-249

Dear Mr. Giambusso:

A report concerning the results of the fuel inspection and evaluation for Dresden Unit 3 was submitted on August 12, 1971 as Special Report No. 16.

After review of the specific rods replaced in the Dresden Unit 3 fuel bundles due to deviations in enrichment, an error was noted in the report submitted on August 12. The following numbers were in error: 454 rods replaced should now read 441 rods replaced; 88 deviating rods used in the Dresden 3 fuel bundles should now read 101 deviating rods have been used in the Dresden 3 fuel bundles in locations such that their presence will not cause any departure from the design local peaking factor.

In addition to one signed original, 39 copies of this letter are also submitted.

Very truly yours,

Byron Lee, Jr.  
Assistant to the President

