




Commonwealth Edison
 One First National Plaza, Chicago, Illinois
 Address Referred to: Post Office Box 767
 Chicago, Illinois 60690

BBS Ltr. #463-75

Dresden Nuclear Power Station
 R.R. #1
 Morris, IL 60450

Regulatory



July 30, 1975



Mr. James G. Keppler
 Regional Director
 Directorate of Regulatory Operation - Region III
 U.S. Nuclear Regulatory Commission
 799 Roosevelt Road
 Glen Ellyn, IL 60137

SUBJECT: Follow-up Report to Abnormal Occurrence Entitled "Cracks In Control Rod Drive Collet Housings" (Report No. 50-249/1975-31)

Report No. 50-249/1975-31A

Dear Mr. Keppler:

Please find attached the "Summary Report of the Investigatory Work Performed on Dresden 3 Control Rod Drive Collet Housing Cracks." This report is submitted in accordance with the commitment specified under "Corrective Action" of Report No. 50-249/1975-31.

Sincerely,

Arthur M. Roberts

for B.B. Stephenson
 Superintendent
 Dresden Nuclear Power Station

BBS:TJK:aw

cc: File/NRC

Enc.

8677

AUG 4 1975