


DR Control file



50249 telegram

DEB900 SSE237

DE JLAG99 BJ PD MORRIS 31 1107A CST= 1971 DEC 31 PM 1 30  
MR BOYCE W GRIER=DIRECTOR US ATOMIC ENERGY COMMISSION  
REGION3=COMPLIANCE 799 ROOSEVELT RD X GLENELLYN ILL

=THIS IS TO CONFIRM TELEPHONE CONVERSATION WITH MR HUGH  
DANCE REGION THREE COMPLIANCE CONCERNING SECTION 3.8.0B  
DPR25 TECHNICAL SPECIFICATION. AT APPROXIMATELY 2310 HOURS  
ON DECEMBER 30 1971 ONE OF THE MECHANICAL VACUUM PUMP  
SUCTION VALVES DID NOT FULLY CLOSE FOLLOWING REVERSING THE  
MAIN CONDENSER CIRCULATION WATER FLOW. THE UNIT WAS AT  
150MWE IN PREPARATION OF COMING OFF SYSTEM FOR A PLANNED  
OUTAGE. FAILURE OF THIS VALVE TO FULLY CLOSE WOULD  
HAVE PREVENTED THE MECHANICAL VACUUM PUMP FROM BEING

ISOLATED AS REQUIRED BY SECTION 3.8.0B IF IT RECEIVED AN  
ISOLATION SIGNAL. THE MANUAL SUCTION VALVE WAS CLOSED AND  
THE REACTOR PLACED IN A COLD SHUTDOWN CONDITION. =  
W P WORDEN=SUPT DRESEDEN NUCLEAR POWER STATION. =

TELEPHONE NO. 858-2660  
TELEPHONED TO: See  
TIME DELIVERED: 946 1/3/72  
BY: GE AT THE: me  
*See 1336*  
*See 28*  
*See 258*  
*See 304*  
*444*

1 5105

JAN 3 1972