



Commonwealth Edison
 One First National Plaza, Chicago, Illinois
 Address Reply to: Post Office Box 767
 Chicago, Illinois 60690

BBS Ltr.#473-74

50-249

Dresden Nuclear Power Station
 R. R. #1
 Morris, Illinois 60450
 July 1, 1974

Regulatory Docket File



Mr. J. F. O'Leary, Director
 Directorate of Licensing
 U. S. Atomic Energy Commission
 Washington, D. C. 20545

**SUBJECT: INSPECTION OF UNIT THREE DRYWELL SHOCK SUPPRESSORS,
 DRESDEN NUCLEAR POWER STATION.**


Dear Mr. O'Leary:

This letter is to report the results of the inspection of Dresden Station Unit 3 drywell snubbers. Since the unit was to be in the shutdown condition for greater than a 24 hour period, a drywell snubber inspection was performed. On June 28, 1974, thirty-five drywell snubbers, eight turbine pipeway snubbers, and three isolation condenser snubbers were inspected. Of the 46 total snubbers, only four were found to be low on fluid. All four of the snubbers low on fluid were located inside the drywell. Of the four low on fluid, none were considered to be inoperable. The four low snubbers were filled to their proper level prior to startup of the unit.

Sincerely,

B. B. Stephenson
 B. B. Stephenson
 Superintendent

BBS:TEL:do



6332