

UNITED STATES  
NUCLEAR REGULATORY COMMISSION  
OFFICE OF INSPECTION AND ENFORCEMENT  
REGION III  
799 ROOSEVELT ROAD  
GLEN ELLYN, ILLINOIS 60137

A. IE Inspection Report No. \_\_\_\_\_

Transmittal Date : \_\_\_\_\_

Distribution:  
IE Chief, FS&EB  
IE:HQ (5)  
DR Central Files  
Regulatory Standards (3)  
Licensing (13)  
IE Files

Distribution:  
IE Chief, FS&EB  
IE:HQ (4)  
L:D/D for Fuels & Materials  
DR Central Files  
IE Files  
IE Chief, M&PPB  
L:D/D for Reactor Project

B. IE Inquiry Report No. \_\_\_\_\_

Transmittal Date : \_\_\_\_\_

Distribution:  
IE Chief, FS&EB  
IE:HQ (5)  
DR Central Files  
Regulatory Standards (3)  
Licensing (13)  
IE Files

Distribution:  
IE Chief, FS&EB  
IE:HQ  
DR Central Files  
IE Files

C. Incident Notification From: Commonwealth Edison Company 50-249  
(Licensee & Docket No. (or License No.))

Transmittal Date : July 31, 1975 Dresden Station Unit 3

Distribution:  
IE Chief, FS&EB  
IE:HQ (4)  
Licensing (4)  
DR Central Files  
IE Files

Distribution:  
IE Chief, FS&EB  
IE:HQ (4)  
L:D/D for Fuels & Materials  
DR Central Files  
IE Files



James G. Keppler, Regional Director  
Directorate of Regulatory Operations  
Region III  
U.S. Nuclear Regulatory Commission  
799 Roosevelt Road  
Glen Ellyn, IL 60137

Teletyped

Date

7-22-75

GE

11:23 A.M.

DC

11:14 A.M.

By

JK

cc:  
Bernard C. Rusche, Director  
Directorate of Licensing  
U.S. Nuclear Regulatory Commission  
Washington, D.C. 20555

50-249

SUBJECT: DPZ-25, Dresden Nuclear Power Station, Unit 3.

This will confirm a conversation with Mr. P. Johnson of your office at 0820 hrs this date concerning LOCATION OF BROKEN TACK WELDS ON JET pump RESTRAINER CLAMP BOLT KEEPERS DURING TV CAMERA EXAMINATION OF UNIT 3 JET pumps #6 AND #17. STRUCTURAL INTEGRITY OF THE JET pumps WERE FOUND SATISFACTORY AND NO PARTS WERE BROKEN LOOSE FROM THE RETAINER. ONLY ONE OF THE TWO CLAMP BOLT KEEPERS ON EACH JET pump WERE AFFECTED. REPAIR WILL CONSIST OF UNDERWATER TACK WELDING OF THE KEEPERS IN PLACE FOLLOWING TORQUE MEASUREMENTS OF THE CLAMP BOLTS IS FOUND SATISFACTORY.

To Call:

GE - 5-858-2660x16 (auto)

DC - 9-1-301-492-7617 (auto)

NU - 815-942-4649/4621

Station Dist: Originator (copy)  
Incident File (copy)  
Telegram File (original)

B. B. Stephenson, Superintendent  
Dresden Nuclear Power Station  
Commonwealth Edison Company  
R.E. 61  
Morris, IL 60450

Telephone: 815-942-2920/7921x212

30 7/21/75 LS