



UNITED STATES  
NUCLEAR REGULATORY COMMISSION  
~~ATOMIC ENERGY COMMISSION~~  
DIRECTORATE OF REGULATORY OPERATIONS  
REGION III  
799 ROOSEVELT ROAD  
GLEN ELLYN, ILLINOIS 60137

249

TELEPHONE  
(312) 858-2660

A. RO Inspection Report No. \_\_\_\_\_

Transmittal Date : \_\_\_\_\_

Distribution:  
RO Chief, FS&EB  
RO:HQ (5)  
DR Central Files  
Regulatory Standards (3)  
Licensing (13)  
RO Files

Distribution:  
RO Chief, FS&EB  
RO:HQ (4)  
L:D/D for Fuels & Materials  
DR Central Files  
RO Files

B. RO Inquiry Report No. \_\_\_\_\_

Transmittal Date : \_\_\_\_\_

Distribution:  
RO Chief, FS&EB  
RO:HQ (5)  
DR Central Files  
Regulatory Standards (3)  
Licensing (13)  
RO Files

Distribution:  
RO Chief, FS&EB  
RO:HQ  
DR Central Files  
RO Files

C. Incident Notification From: Commonwealth Edison Co., Docket No. 50-249  
(Licensee & Docket No. (or License No.))

Transmittal Date : JAN 28 1975

Distribution:  
RO Chief, FS&EB  
RO:HQ (4)  
Licensing (4)  
DR Central Files  
RO Files

Distribution:  
RO Chief, FS&EB  
RO:HQ (4)  
L:D/D for Fuels & Materials  
DR Central Files  
RO Files

AO  
4



# Telegram

1975 JAN -8 PM 4: 18  
dc-d

VEB247(1710)(2-030655E006)PD 01/06/75 1710

ICS IPMBNGZ CSP

TELEPHONE NBR. 312-858-2660  
TELESTIMED TO P. J.  
DATE DLD 1/7 TIME 9:58 BY 94  
REGIONAL DIRECTOR, S. ATOMIC  
MAD

8159424449 TDBN MORRIS IL 60 01-06 0510

PMS JAMES G KEPPLER, REGIONAL DIRECTOR

DIRECTORATE OF REGULATORY OPERATIONS -

ENERGY COMMISSION 799 ROOSEVELT RD

GLEN ELLYN IL 60137

SUBJECT: DPR-25, DRESDEN NUCLEAR POWER STATION UNIT 3.

THIS WILL CONFIRM A CONVERSATION WITH PHIL JOHNSON OF YOUR OFFICE AT 1445 HOURS THIS DATE CONCERNING FAILURE OF TWO BERGAN-PATERSON PIPE RESTRAINTS IN UNIT THREE DRYWELL. BOTH SNUBBERS WERE REPLACED FOLLOWING THEIR DISCOVERY ON 4 JANUARY 75. SEALED MATERIAL IN BOTH CASES WAS ETHYLENE-PROPYLENE.

D B STEPHENSON SUPERINTENDENT DRESDEN NUCLEAR POWER STATION

COMMONWEALTH EDISON CO RR 1 MORRIS ILLINOIS 60450

JAN 9 1975

SF-1201 (R5-69)

P