

UNITED STATES
ATOMIC ENERGY COMMISSION
DIVISION OF COMPLIANCE
REGION III
799 ROOSEVELT ROAD
GLEN ELLYN, ILLINOIS 60137

TELEPHONE
(312) 858-2660

50-249

A. RO Inspection Report No. _____

Transmittal Date : _____

Distribution:
RO Chief, FS&EB
RO:HQ (5)
DR Central Files
Regulatory Standards (3)
Licensing (13)

Distribution:
RO Chief, FS&EB
RO:HQ (4)
L:D/D for Fuel & Materials
DR Central Files

B. RO Inquiry Report No. _____

Transmittal Date : _____

Distribution:
RO Chief, FS&EB
RO:HQ (5)
DR Central Files
Regulatory Standards (3)
Licensing (13)

Distribution:
RO Chief, FS&EB
RO:HQ
DR Central Files

C. Incident Notification From: Commonwealth Edison Co. DPR-25
(Licensee & Docket No. (or License No.))

Transmittal Date : August 6, 1973

Distribution:
RO Chief, FS&EB
RO:HQ (4)
Licensing (4)
DR Central Files
RO Files

Distribution:
RO Chief, FS&EB
RO:HQ (4)
L:D/D for Fuel & Materials
DR Central Files

AbnOw

BND106(1004)(1-007727C212)PD 07/31/73 1002

ICS IPMVEIC MVN

03038 (03228) TDVE MORRIS ILL 93 07-30 330P CDT

FON 3128582660


BOYCE BRIER DIRECTOR DIV OF COMPLIANCE
REGION E US ATOMIC ENERGY COMMISSION 799
ROOSEVELT RD GLEN ELLYN IL 60137

SUBJECT DPR-25 DRESDEN NUCLEAR POWER STATION UNIT 3.
THIS WILL CONFIRM A CONVERSATION WITH MR F MAURA OF YOUR OFFICE
AT 1030 HOURS THIS DATE CONCERNING FAST CLOSURE TIME ON 1B
MAIN STEAM ISOLATION VALVE. ON 7/29/73 DURING A UNIT STAT UP 1B MSIV
WAS TIMED AND FOUND TO HAVE A CLOSURE TIME OF 2.6 SECONDS.
CABLE 3.7.1 OF TECHNICAL SPECIFICATIONS REQUIRES A CLOSURE TIME OF BE

SF-1201 (R5-69)

BETWEEN 3 AND 5 SECONDS

UNTIL PROBLEMS CAN BE CORRECTED, MSIVS 1 B AND 2 B WILL REMAIN CLOSED
W P WARDEN SUPERINTENDENT DRESDEN NUCLEAR POWERSTATION



power

AUG 3 1973

SF-1201 (R5-69)