

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 8409060213 DOC. DATE: 84/08/30 NOTARIZED: NO DOCKET #
 FACIL: 50-244 Robert Emmet Ginna Nuclear Plant, Unit 1, Rochester G 05000244
 AUTH. NAME AUTHOR AFFILIATION
 KOBER, R.W. Rochester Gas & Electric Corp.
 RECIP. NAME RECIPIENT AFFILIATION
 PAULSON, W.A. Operating Reactors Branch 5

SUBJECT: Updates several commitments described in SER (NUREG-0944) re full-term OL. High energy sources removed from control bldg. Seismic piping upgrade program mods will be completed during 1985 & 1986 refueling outages.

DISTRIBUTION CODE: A001D COPIES RECEIVED: LTR 1 ENCL 0 SIZE: 2
 TITLE: OR Submittal: General Distribution

NOTES: NRR/DL/SEP 1cy. 05000244
 OL: 09/19/69

	RECIPIENT ID CODE/NAME		COPIES LTR ENCL		RECIPIENT ID CODE/NAME		COPIES LTR ENCL
	NRR ORB5 BC	01	7				
INTERNAL:	ADM/LFMB		1		ELD/HDS4		1
	NRR/DE/MTEB		1		NRR/DL DIR		1
	NRR/DL/ORAB		1		NRR/DSI/METB		1
	NRR/DSI/RAB		1		<u>REG FILE</u>	04	1
	RGN1		1				
EXTERNAL:	ACRS	09	6		LPDR	03	1
	NRC PDR	02	1		NSIC	05	1
	NTIS		1				
NOTES:			1				

TOTAL NUMBER OF COPIES REQUIRED: LTR 27 ENCL 0

Faint, illegible text at the top of the page, possibly a header or title area.


Section of text, possibly a paragraph or a list of items, located in the upper middle part of the page.

Section of text, possibly a paragraph or a list of items, located in the middle part of the page.

ITEM	DESCRIPTION	QUANTITY	UNIT PRICE
1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16
17
18
19
20
21
22
23
24
25
26
27
28
29
30
31
32
33
34
35
36
37
38
39
40
41
42
43
44
45
46
47
48
49
50



ROCHESTER GAS AND ELECTRIC CORPORATION • 89 EAST AVENUE, ROCHESTER, N.Y. 14649-0001



ROGER W. KOBER
VICE PRESIDENT
ELECTRIC & STEAM PRODUCTION

TELEPHONE
AREA CODE 716 546-2700

August 30, 1984

Director of Nuclear Reactor Regulation
Attention: Mr. Walter A. Paulson, Acting Chief
Operating Reactors Branch No. 5
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

Subject: FTOL Supplement
R. E. Ginna Nuclear Power Plant
Docket No. 50-244

Dear Mr. Paulson:

The purpose of this letter is to update several commitments described in NUREG-0944, the R. E. Ginna "Safety Evaluation Report Related to the Full-Term Operating License," October 1983.

1. Section 3.5 - RG&E committed to eliminate high energy steam lines from the relay room and air handling room. This commitment was met during the 1984 refueling outage by removing the sources of high energy from the control building. The steam supply and relief lines and condensate return lines have been cut and capped or welded outside the control building.
2. Section 3.6(2) - RG&E stated that the seismic piping upgrade program was expected to be completed by the end of the 1984 refueling outage. The majority of this effort has been accomplished. However, some additional analysis and installation must still be performed. RG&E expects to complete any additional modifications, if necessary, during the 1985 and 1986 refueling outages.
3. Section 3.6(3) - RG&E committed to provide additional seismic support for the four essential service water pumps and the component cooling water surge tank. Both of these modifications were completed prior to the end of the 1984 refueling outage.
4. Section 3.6(3)(b) - RG&E committed to provide additional seismic support for the sodium hydroxide tank. This modification was completed prior to the end of the 1984 refueling outage.

8409060213 840830
PDR ADDCK 05000244
P PDR

Acc'l
1/0

6 Nov 10

Director of the FBI
Washington, D.C.
Dear Sir:

Enclosed for you are
two copies of the report

of the investigation
conducted at New York

on 10/25/54
by SA [Name]

DATE August 30, 1984

TO Mr. Walter A. Paulson

5. Section 3.6(4) - RG&E committed to complete the analysis and submit the report concerning the seismic capability of the main control board. This report, entitled "Seismic Structural Evaluation of the Main Control Board," was submitted with RG&E's letter of January 9, 1984 relative to SEP Topic III-6, "Seismic Design Considerations". Based on the recommendations contained in that report, RG&E determined that modifications to enhance the structural integrity of the main control board should be performed. These modifications were completed during the 1984 refueling outage.
6. Section 6.2 - RG&E proposed to implement a number of modifications, both procedural and hardware, relative to the containment fluid system penetrations. The procedural modifications, which consisted of locking certain valves in position and performing Appendix J Type "C" leak testing on them, were completed during the 1984 refueling outage. The hardware modifications, which include the addition of another valve in the seal return line and the enhancement of the fan cooler service water isolation valves, are scheduled to be completed during the 1986 refueling outage.
7. Section 9.2 - RG&E proposed to add a redundant component cooling water surge tank level indication in the control room. This modification was completed prior to the end of the 1984 refueling outage.

Very truly yours,



Roger W. Kober

Roger W. Kober

1944

1944
1944
1944
1944

1944

1944
1944

1944
1944

1944
1944