ACCELERATED DISTRIBUTION DEMONSTRATION SYSTEM

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

CESSION NBR:9003160299 DOC.DATE: 90/03/09 NOTARIZED: NO DOCKET #
FACIL:50-244 Robert Emmet Ginna Nuclear Plant, Unit 1, Rochester G 05000244
AUTH.NAME AUTHOR AFFILIATION

JOHNSON, J.R. Region 1, Of

Region 1, Ofc of the Director

RECIP.NAME MECREDY, R.

RÉCIPIENT AFFILIATION Rochester Gas & Electric Corp.

SUBJECT: Forwards Saefty Insp Rept 50-244/90-02 on 900109-0220 &

notice of violation.

DISTRIBUTION CODE: IE01D COPIES RECEIVED:LTR | ENCL / SIZE: 2+12
TITLE: General (50 Dkt)-Insp Rept/Notice of Violation Response

NOTES:License Exp date in accordance with 10CFR2,2.109(9/19/72). 05000244

	RECIPIENT ID CODE/NAME PD1-3 PD	COPII LTTR 1	es Encl 1	RECIPIENT ID CODE/NAME JOHNSON,A	COPI LTTR 1	
INTERNAL:	AEOD AEOD/TPAD NRR SHANKMAN,S NRR/DOEA DIR 11 NRR/DREP/PRPB11 NRR/DST/DIR 8E2 NUDOCS-ABSTRACT REG FILE 02 RGN1 FILE 01	1 1 2 1 1 1	1 1 1 2 1 1	AEOD/DEIIB DEDRO NRR/DLPQ/LPEB10 NRR/DREP/PEPB9D NRR/DRIS/DIR NRR/PMAS/ILRB12 OGC/HDS2 RES MORISSEAU,D	1 1 1 1 1	1 1 1 1 1 1
EXTERNAL:	LPDR NSIC	1	1	NRC PDR	1	1

NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK, ROOM PI-37 (EXT. 20079) TO ELIMINATE YOUR NAME FROM DISTRIBUTION LISTS FOR DOCUMENTS YOU DON'T NEED!

OTAL NUMBER OF COPIES REQUIRED: LTTR 23 ENCL 23

R I D

F

T.

S

r

Γ

S /

A

D

S

Docket No. 50-244

Rochester Gas and Electric Corporation ATTN: Dr. Robert Mecredy General Manager Nuclear Production 49 East Avenue Rochester, New York 14649

Gentlemen:

Subject: Inspection 50-244/90-02 (01/09/90 - 02/20/90)

This refers to the routine safety inspection conducted on January 9 through February 20, 1990, at the R. E. Ginna nuclear power plant by NRC Region I. At the end of the inspection period, Messrs. C. Marschall and N. Perry of my staff discussed the inspection findings with Mr. S. Spector and other members of your staff.

As set forth in the enclosed Notice of Violation, RG&E personnel failed to promptly correct an inadequate method for verifying position of the steam admission check valves in the auxiliary feedwater system. The resident inspectors questioned the adequacy of this method of verification during a previous surveillance in December 1989, but the concern was not appropriately addressed. Please respond to this violation as specified in Enclosure 1.

Your cooperation is appreciated.

Sincerely,

CRIGHTAL SIGNED BY:

Jon R. Johnson, Chief Projects Branch 3 Division of Reactor Projects

Enclosure:

Appendix A, Notice of Violation

NRC Region I Inspection Report 50-309/90-02

cc w/encl:
Harry H. Voigt, Esquire
Central Records (4 copies)
Director, Power Division
Public Document Room (PDR)
Local Public Document Room (LPDR)
Nuclear Safety Information Center (NSIC)
NRC Resident Inspector
State of New York, Department of Law
State of New York, SLO Designee

OFFICIAL RECORD COPY

IR GINNA 90-02 - 0001.0.0 03/01/90

IFOI

9003160299 900309 PDR ADOCK 05000244 Q PDC bcc w/encl:

Region I Docket Room (with concurrences) Management Assistant, DRMA (w/o encls)

E. McCabe, DRP

A. Johnson, PM, NRR J. Johnson, DRP

J. Dyer, EDO

J. Strosnider, DRS (see Detail 4.2) R. Keimig, DRSS (see Detail 4.1)

DRP:RI Marschall 2/26/90 317

DRP:RI Perry 317

DRP:RI McCabe

OFFICIAL RECORD COPY

IR GINNA 90-02 - 0002.0.0 11/29/80