CATEGORY 2

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR:9811240060 DOC.DATE: 98/11/19 NOTARIZED: NO DOCKET # FACIL:50-244 Robert Emmet Ginna Nuclear Plant, Unit 1, Rochester G 05000244 AUTH.NAME AUTHOR AFFILIATION

DOERFLEIN, L.T. Region 1 (Post 820201)
RECIP.NAME RECIPIENT AFFILIATION

MECREDY, R.C. Rochester Gas & Electric Corp.

SUBJECT: Forwards insp rept 50-244/98-11 on 980907-1018. No violations noted. Staff coordinated well with Westinghouse representatives in correcting deficiencies in refurbished service water pump circuit breaker.


DISTRIBUTION CODE: IE01F. COPIES RECEIVED:LTR ___ ENCL ___ SIZE: _____ 5 + 28 TITLE: General (50 Dkt)-Insp Rept/Notice of Violation Response

NOTES:License Exp date in accordance with 10CFR2,2.109(9/19/72). 05000244

,	RECIPIENT ID CODE/NAME PD1-1 PD	COPIES LTTR ENCL 1 1	RECIPIENT ID CODE/NAME VISSING,G.	COPIES LTTR ENCL 1 1	
INTERNAL:	AEOD/SPD/RAB DEDRO · NRR/DRCH/HOHB NRR/DRPM/PERB OE DIR RGN1 FILE 01	1 1 1 1 1 1 1 1 1 1	AEOD/ATC FILE CENTER NRR/DRPM/PECB NUDOCS-ABSTRACT OGC/HDS3	1 1 1 1 1 1 1 1 1 1	
EXTERNAL:	LITCO BRYCE, J.H NRC PDR	1 1 1 1	NOAC NUDOCS FULLTEXT	1 1 1 1	

LOADED FROM ELECTRONIC FILE

NOTE TO ALL "RIDS" RECIPIENTS:
PLEASE HELP US TO REDUCE WASTE. TO HAVE YOUR NAME OR ORGANIZATION REMOVED FROM DISTRIBUTION LIST:
OR REDUCE THE NUMBER OF COPIES RECEIVED BY YOU OR YOUR ORGANIZATION, CONTACT THE DOCUMENT CONTRO)
DESK (DCD) ON EXTENSION 415-2083



Dr. Robert C. Mecredy Vice President, Ginna Nuclear Operations Rochester Gas and Electric Corporation 89 East Avenue Rochester, New York 14649

SUBJECT: NRC INTEGRATED INSPECTION REPORT 50-244/98-11

Dear Dr. Mecredy:

This letter transmits the results of safety inspections conducted by NRC inspectors at the Ginna Nuclear Power Plant from September 7, 1998 through October 18, 1998. At the conclusion of the inspection, the findings were discussed with Mr. J. Widay and others of your staff.

During the six week period covered by this inspection period, we noted good sustained plant operation. Your staff coordinated well with Westinghouse representatives in correcting deficiencies in a refurbished service water pump circuit breaker. The performance of spent fuel pool re-rack activities continues to go well, and personnel exposure levels for this effort have remained low.

In accordance with 10 CFR 2.790 of the NRC's "Rules of Practice," a copy of this letter and its enclosures will be placed in the NRC Public Document Room (PDR).

Sincerely,

Original Signed by: William A. Cook for


Lawrence T. Doerflein, Chief Projects Branch 1 Division of Reactor Projects

Docket No.: 50-244 License No: DPR-18

Enclosures: Inspection Report 50-244/98-11

201

7811240060 781119 PDR ADDCK 05000244 G PDR





cc w/encl:

P. Wilkens, Senior Vice President, Generation

Central Records (7 copies)

- P. Eddy, Electric Division, Department of Public Service, State of New York
- C. Donaldson, Esquire, State of New York, Department of Law
- N. Reynolds, Esquire
- F. William Valentino, President, New York State Energy Research and Development Authority
- J. Spath, Program Director, New York State Energy Research and Development Authority

Ø



R. C. Mecredy .

Distribution w/encl:

H. Miller, RA/W. Axelson, DRA (1)

Region I Docket Room (with concurrences)

PUBLIC

NRC Resident Inspector

Nuclear Safety Information Center (NSIC)

L. Doerflein, DRP

W. Cook, DRP

R. Junod, DRP

Distribution w/encl (VIA E-MAIL):

B. McCabe, RI EDO Coordinator

S. Bajwa, NRR

G. Vissing, NRR

M. Campion, ORA

Inspection Program Branch, NRR (IPAS)

R. Correia, NRR

DOCDESK

DOCUMENT NAME: G:\BRANCH1\GIN9811.INS

To receive a copy of this document, indicate in the box: "C" = Copy without attachment/enclosure "E" = Copy with attachment/enclosure "N" = No copy

11	RI/DRP	RI/DRP
NAME	PDrysdale W	LDoerflein W
DATE	11/9/98	11/98 . 100

OFFICIAL RECORD COPY

