

LICENSEE EVENT REPORT

CONTROL BLOCK: | | | | | | | 1

(PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01	F	I	L	S	I	S	I	1	2	0	1	0	-	0	1	0	0	0	0	1	-	1	0	3	4	1	1	1	1	1	4	1	5
7	3	3	LICENSEE CODE	14	73	LICENSE NUMBER	35	36	LICENSE TYPE	JO	37	CAT	38	39																			

CONT

CONT'D
REPORT SOURCE L 5 0 1 5 1 0 1 0 1 3 1 3 1 5 7 0 1 8 1 0 1 5 1 8 1 0 1 3 0 1 9 1 0 1 3 1 8 1 0 9
7 8 9 50 61 COCKET NUMBER 62 63 64 65 EVENT DATE 71 72 73 74 75 REPORT DATE 76 77 78 79

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

[013] During full power operation CEA 23 dropped to full insertion. Action per
[013] TS 3.1.3.1e was initiated. Rx power was reduced to 70%, CEA 23 was
[014] repaired, tested and realigned with its group. Power was increased to 100%.
[015] Similar occurrences were reported in LER's 335-80-23, 80-10, 80-7, 80-2,
[016] 80-32, 80-34, 80-35.

018

013

SYSTEM CODE		CAUSE CODE		CAUSE SUBCODE		COMPONENT CODE		COMP. SUBCODE		VALVE SUBCODE													
0	1	R	I	B	(1)	E	(12)	E	(13)	I	N	S	T	I	R	U	(14)	P	(15)	Z	(16)		
7	8	9	10	11		12		13		14		15		16		17		18		19		20	
(17) LERIRO REPORT NUMBER		EVENT YEAR		SEQUENTIAL REPORT NO.		OCCURRENCE CODE		REPORT TYPE		REVISION NO.													
17		8 1 0		0 1 3 1 6		0 1 3		L		0													
ACTION TAKEN		FUTURE ACTION		EFFECT ON PLANT		SHUTDOWN METCODE		ATTACHMENT SUBMITTED		WARD FORM SUB.		PRIME COMP. SUPPLIER		COMPONENT MANUFACTURER									
A	(18)	Z	(19)	B	(20)	Z	(21)	0	0	0	4	N	(22)	N	(23)	N	(24)	N	(25)	P	3	1	4
33	34	35	36	37	38	39	40	41	42	43	44	45	46	47									

CEA 23 dropped due to a failure in its core power programmer 15v power supply. The power supply was replaced. A modification is underway to provide redundant 15v power supplies to each CEA.

13

三

12.3.2

FACILITY STATUS			POWER			OTHER STATUS			METHOD OF DISCOVERY			DISCOVERY DESCRIPTION		
1	5	E	(23)	1	1	0	1	0	(3)	NA	A	(31)	OPERATOR	OBSERVATION
7	8	2	10	11	12	13	14	15	16		45	46		
ACTIVITY CONTENT			RELEASED OR RELEASE			AMOUNT OF ACTIVITY						LOCATION OF RELEASE		
1	5	Z	(30)	1	7	(7)	NA							
7	8	3	13	14	15	16	17	18	19	20				
PERSONNEL EXPOSURES			NUMBER			TYPE			DESCRIPTION			DISCRIPTION		
1	1	7	1	0	1	0	1	0	1	0	NA			
7	8	3	11	12	13	14	15	16	17	18				
PERSONNEL INVOLVED			NUMBER			TYPE			DESCRIPTION			DISCRIPTION		
1	1	3	1	0	1	0	1	0	1	0	NA			
7	8	3	11	12	13	14	15	16	17	18				
LOSS OF OR DAMAGE TO FACILITY			TYPE			DESCRIPTION								
1	1	9	Z	(42)		NA								
7	8	3	16	17	18	19	20	21	22	23				
PUBLICITY			REQUEST			DESCRIPTION						NRC USE ONLY		
1	1	0	N	(43)		NA								
7	8	3	16	17	18	19	20	21	22	23				

Digitized by srujanika@gmail.com

P.L. Pace

PHONE: (305) .552-3801

8009150290