



UNITED STATES  
NUCLEAR REGULATORY COMMISSION  
REGION V  
1990 N. CALIFORNIA BOULEVARD  
SUITE 202, WALNUT CREEK PLAZA  
WALNUT CREEK, CALIFORNIA 94596

CF

JUN 11 1979

Docket No. 50-397

Washington Public Power Supply System  
P. O. Box 968  
Richland, Washington 99352

Attention: Mr. N. O. Strand  
Managing Director

Gentlemen:


Subject: Report on Deficiency Involving Defective Steel Plate In Supporting Structures for Pipe Whip Restraints, WNP No. 2 (your letter of May 31, 1979)

Thank you for your letter, referenced above, which forwarded a report pursuant to 10 CFR 50.55(e) regarding the subject matter.

Your report will be reviewed and evaluated and should we require additional information concerning this matter, we will contact you.

Your cooperation with us is appreciated.

Sincerely,

  
R. H. Engelken  
Director

MR-1

7907180541

60