

Washington Public Power Supply System
A JOINT OPERATING AGENCY

P. O. Box 968

3000 GEO. WASHINGTON WAY

RICHLAND, WASHINGTON 99352


PHONE (509) 375-5000

October 18, 1979
G02-79-191

Nuclear Regulatory Commission
Region V
Office of Inspection and Enforcement
Suite 202, Walnut Creek Plaza
1900 N. California Boulevard
Walnut Creek, California 94596

Attention: Mr. R. H. Engelken, Director

Subject: WPPSS NUCLEAR PROJECT NO. 2
DOCKET NUMBER 50-397, CPPR-93
REPORTABLE DEFICIENCY - 10CFR50.55(e)



Dear Mr. Engelken:

In accordance with the provisions of 10CFR50.55(e), your staff was informed by telephone on September 21, 1979, of a reportable condition involving the spent fuel pool cooling system which is not designed to Seismic Category 1 standards.

Attached is our report of this deficiency. Action to correct this condition is currently being evaluated. A final report of action taken will be forwarded to your office before November 30, 1979.

Please contact us if you have additional questions.

Very truly yours,

D. L. RENBERGER
Assistant Director
Technology

DLR/GLC/jdb

Attachment: As stated

cc: JJ Verderber - B&R, w/att
JJ Byrnes - B&R, w/att
JR Lewis - BPA, w/att
JG Davis, Director, NRC, Washington, D.C., w/att
WNP-2 Files, w/att

7911200051
50-129