

mal

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR:8004280466 DOC.DATE: 80/04/21 NOTARIZED: NO DOCKET #
FACIL:50-397 WPPSS Nuclear Project, Unit 2, Washington Public Powe 05000397
AUTH.NAME AUTHOR AFFILIATION
RENBERGER,D.L. Washington Public Power Supply System
RECIP.NAME RECIPIENT AFFILIATION
ENGELKEN,R.H. Region 5, San Francisco, Office of the Director

SUBJECT: Forwards deficiency rept re small bore piping design.

DISTRIBUTION CODE: B019B COPIES RECEIVED:LTR 1 ENCL 1 SIZE: 1x1
TITLE: Construction Deficiency Report (10CFR50.55E)


NOTES: PM. 2 CYS ALL MATL.

	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL
ACTION:	14 PM <u>M. LYNCH</u>	1 1	15 BC <u>LWR #4</u>	1 1
	20 LA <u>LWR #4</u>	1 1	21 AD <u>LWR</u>	1 1
INTERNAL:	01 <u>REG FILE</u>	1 1	02 NRC PDR	1 1
	05 <u>I&E</u>	2 2	07 EDO & STAFF	1 1
	08 MPA	1 1	09 DEPY DIR DPM	1 1
	10 QAB	1 1	11 STANDRDS DEV	1 1
	13 FIELD COOR/IE	1 1	16 AD FOR ENGR	1 1
	17 AD PLANT SYS	1 1	17 AD REAC SFTY	1 1
	22 DIR DPM	1 1	23 OELD	1 1
	AD/RCI/IE	1 1	AD/SITE TECH	1 1
	AEOD	1 1	DIRECTOR DSE	1 1
	GEOSCIENCES BR	1 1	HANAUER, S.	1 1
	I&C SYS BR	1 1	MATL ENG BR	1 1
	MECH ENG BR	1 1	POWER SYS BR	1 1
	STRUCT ENG BR	1 1		
EXTERNAL:	03 LPDR	1 1	04 NSIC	1 1
	24 ACRS	16 16		

APR 29 1980

T

TOTAL NUMBER OF COPIES REQUIRED: LTTR 50 ENCL 50
48 48



Washington Public Power Supply System
A JOINT OPERATING AGENCY

P. O. Box 968

3000 GEO. WASHINGTON WAY

RICHLAND, WASHINGTON 99352

PHONE (509) 375-5000

April 21, 1980

G02-80-94

Nuclear Regulatory Commission
Region V
Office of Inspection and Enforcement
Suite 202, Walnut Creek Plaza
1990 N. California Blvd.
Walnut Creek, California 94596

Attention: Mr. R. H. Engelken, Director

Subject: WPPSS NUCLEAR PROJECT NO. 2
DOCKET NO. 50-397, CPPR-93
REPORTABLE DEFICIENCY - 10CFR50.55(e)

Dear Mr. Engelken:

In accordance with the provisions of 10CFR50.55(e), your staff was informed by telephone on March 19, 1980, of a reportable condition regarding small bore piping design.

Attached is our report concerning this deficiency.

Please contact us if you have additional questions.

Very truly yours,

D. L. Renberger
Assistant Director, Technology

DLR/RTJ/im

Attachment: As stated

cc: JR Lewis, BPA w/1

· JJ Byrnes, B&R w/1

V Stello, Director, NRC, WDC w/1

JJ Verderber, B&R, w/1

WNP-2 Files w/1

LIS-NUS Corporation w/1

B019
SE
1/1

8004280466