

# CATEGORY 1

## REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 9808030029 DOC.DATE: 98/07/23 NOTARIZED: NO DOCKET #  
 FACIL: 50-397 WPPSS Nuclear Project, Unit 2, Washington Public Powe 05000397  
 AUTH.NAME AUTHOR AFFILIATION  
 BEMIS, P.R. Washington Public Power Supply System  
 RECIP.NAME RECIPIENT AFFILIATION  
 Records Management Branch (Document Control Desk)

SUBJECT: Forwards LER 98-006-01, discussing results of root cause analysis & addl corrective actions taken to rectify deficiencies in WNP, Unit 2, 10CRF, App R high impedance fault calculations.

DISTRIBUTION CODE: IE22T COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 1+4  
 TITLE: 50.73/50.9 Licensee Event Report (LER), Incident Rpt, etc.

NOTES:

|           | RECIPIENT       |  | COPIES |      | RECIPIENT              |  | COPIES |      |
|-----------|-----------------|--|--------|------|------------------------|--|--------|------|
|           | ID CODE/NAME    |  | LTR    | ENCL | ID CODE/NAME           |  | LTR    | ENCL |
|           | PD4-2 PD        |  | 1      | 1    | POSLUSNY, C            |  | 1      | 1    |
| INTERNAL: | ACRS            |  | 1      | 1    | AEOD/SPD/RAB           |  | 2      | 2    |
|           | AEOD/SPD/RRAB   |  | 1      | 1    | <del>FILE CENTER</del> |  | 1      | 1    |
|           | NRR/DE/ECGB     |  | 1      | 1    | NRR/DE/EELB            |  | 1      | 1    |
|           | NRR/DE/EMEB     |  | 1      | 1    | NRR/DRCH/HICB          |  | 1      | 1    |
|           | NRR/DRCH/HOHB   |  | 1      | 1    | NRR/DRCH/HOMB          |  | 1      | 1    |
|           | NRR/DRPM/PECB   |  | 1      | 1    | NRR/DSSA/SPLB          |  | 1      | 1    |
|           | RES/DET/EIB     |  | 1      | 1    | RGN4 FILE 01           |  | 1      | 1    |
| EXTERNAL: | L ST LOBBY WARD |  | 1      | 1    | LITCO BRYCE, J H       |  | 1      | 1    |
|           | NOAC POORE, W.  |  | 1      | 1    | NOAC QUEENER, DS       |  | 1      | 1    |
|           | NRC PDR         |  | 1      | 1    | NUDOCS FULL TXT        |  | 1      | 1    |

C  
A  
T  
E  
G  
O  
R  
Y  
  
1  
  
D  
O  
C  
U  
M  
E  
N  
T

NOTE TO ALL "RIDS" RECIPIENTS:  
 PLEASE HELP US TO REDUCE WASTE. TO HAVE YOUR NAME OR ORGANIZATION REMOVED FROM DISTRIBUTION LISTS OR REDUCE THE NUMBER OF COPIES RECEIVED BY YOU OR YOUR ORGANIZATION, CONTACT THE DOCUMENT CONTROL DESK (DCD) ON EXTENSION 415-2083

WASHINGTON PUBLIC POWER SUPPLY SYSTEM

P.O. Box 968 • Richland, Washington 99352-0968

July 23, 1998  
GO2-98-133

Docket No. 50-397

U.S. Nuclear Regulatory Commission  
Attn: Document Control Desk  
Washington, DC 20555


Gentlemen:

Subject: **WNP-2, OPERATING LICENSE NPF-21  
LICENSEE EVENT REPORT NO. 98-006-01**

Transmitted herewith is Licensee Event Report No. 98-006-01 for WNP-2. This supplemental report discusses the results of the root cause analysis and additional corrective actions taken to rectify deficiencies in the WNP-2 10 CFR 50 Appendix R high impedance fault calculations. This report is submitted pursuant to 10 CFR 50.73 and discusses the items of reportability, corrective action taken, and action to preclude recurrence.

Should you have any questions or desire additional information pertaining to this letter, please call me or Mr. P. J. Inserra at (509) 377-4147.

Respectfully,



P/R. Bemis  
Vice President, Nuclear Operations  
Mail Drop PE23

//  
Jeiz

Attachment

cc: EW Merschoff - NRC RIV  
DF Kirsch - NRC, WCFO  
C Poslusny, Jr. -NRR  
INPO Records Center - Atlanta, GA

NRC Senior Resident Inspector - MD927N (2)  
DL Williams - BPA, 1399  
PD Robinson - Winston & Strawn

9808030029 980723  
PDR ADOCK 05000397  
S PDR

