



UNITED STATES
NUCLEAR REGULATORY COMMISSION

REGION IV

611 RYAN PLAZA DRIVE, SUITE 400
ARLINGTON, TEXAS 76011-8064

NOV 8 1995

MEMORANDUM FOR: J. E. Dyer, Director, Division of Reactor Projects
FROM: H. J. Wong, Chief, Reactor Projects Branch E *HJW*
SUBJECT: WNP-2 OVERSIGHT PANEL MEETING MINUTES - November 2, 1995

The WNP-2 Oversight Panel convened by conference call on November 2, 1995. The topics discussed included the following:

- The next proposed meetings with the licensee were:
 - (1) December 12, approx. 9:00 - noon (at the Arlington Texas Office) with a pre-meeting in the afternoon of December 11
 - (2) February 15, 20, or 26 (at the WNP-2 site)[H. Wong to coordinate these dates with the licensee]
- Proposed agenda topics for the next Panel meeting with the licensee should be provided to H. Wong by Monday, November 6 with transmittal to J. Dyer by November 8 to support the December meeting.
- Recommendations for inspections at WNP-2 were:
 - Radiation protection: upcoming downpowers to perform control rod drive system component replacement work [R. Barr to provide K. Brockman with possible time frames in November and December to maximize opportunities to observe work activities]
 - Operations: expand T. McKernon's operator licensing examination site visit to include control room observations and/or auxiliary operator observations
 - Maintenance: self and independent verification activities
 - Use of F. Brush (Callaway resident inspector) at WNP-2
 - Use of J. Clifford during site visit the week of 12/4 - engineering and/or operations issues
 - K. Brockman will be at WNP-2 on 11/30 for operator license presentations (should consider possible inspection/review activities)
 - Should consider the use of inspectors which have been to WNP-2 for reinspection efforts (i.e., W. Johnson, F. Ringwald, W. Walker)

9809140360 980904
PDR ADOCK 05000397
P PDR



- Followup of the MC 40500 (Corrective Actions) inspection performed by the P. Koltay team should include an assessment of the current status of corrective actions. [K. Brockman to coordinate this inspection followup]
- Augmented operations inspections should occur in the February/March time frame to review pre-outage activities
- The Oversight Panel meeting with the licensee in February 1996 should include discussion of outage activities and planning [H. Wong to coordinate this topic with the licensee]
- J. Clifford's background summary is viewed as an excellent starting point for review of the areas of licensee weakness/inspection focus. Comments on the summary should be submitted to H. Wong. [H. Wong to develop the summary into a suitable document for inspector use in preparation for WNP-2 inspections]

cc:

J. Callan

S. Collins

Oversight Panel Members -

J. Dyer

K. Perkins

K. Brockman

W. Bateman

J. Clifford

H. Wong

R. Barr

B. Henderson

M. Hammond

C. Hackney

D. Kunihiro