

CATEGORY 1

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR:9804010213 DOC.DATE: 98/03/23 NOTARIZED: NO DOCKET #
FACIL:50-397 WPPSS Nuclear Project, Unit 2, Washington Public Powe 05000397
AUTH.NAME, AUTHOR AFFILIATION
COLEMAN,D.W. Washington Public Power Supply System
RECIP.NAME RECIPIENT AFFILIATION
 Document Control Branch (Document Control Desk)

SUBJECT: Submits response to violations noted in NRC insp rept
50-397/97-13. Corrective actions: all pertinent RCIC
components have been upgraded as necessary, w/exception of
two rupture disks.

DISTRIBUTION CODE: IE01D COPIES RECEIVED: LTR 1 ENCL 0 SIZE: 2
TITLE: General (50 Dkt) - Insp Rept/Notice of Violation Response

NOTES:

	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL
	PD4-2 PD	1 1	POSLUSNY, C	1 1
INTERNAL:	ACRS	2 2	AEOD/SPD/RAB	1 1
	AEOD/TTC	1 1	DEDRO	1 1
	FILE CENTER	1 1	NRR/DRCH/HHFB	1 1
	NRR/DRPM/PECB	1 1	NRR/DRPM/PERB	1 1
	NUDOCS-ABSTRACT	1 1	OE DIR	1 1
	OGC/HDS3	1 1	RGN4 FILE 01	1 1
EXTERNAL:	LITCO BRYCE, J H	1 1	NOAC	1 1
	NRC PDR	1 1	NUDOCS FULLTEXT	1 1

NOTE TO ALL "RIDS" RECIPIENTS:
PLEASE HELP US TO REDUCE WASTE. TO HAVE YOUR NAME OR ORGANIZATION REMOVED FROM DISTRIBUTION LISTS
OR REDUCE THE NUMBER OF COPIES RECEIVED BY YOU OR YOUR ORGANIZATION, CONTACT THE DOCUMENT CONTROL
DESK (DCD) ON EXTENSION 415-2083

TOTAL NUMBER OF COPIES REQUIRED: LTR 19 ENCL 0



WASHINGTON PUBLIC POWER SUPPLY SYSTEM

P.O. Box 968 • Richland, Washington 99352-0968

March 23, 1998
GO2-98-060

Docket No. 50-397

U.S. Nuclear Regulatory Commission
Attn: Document Control Desk
Washington, DC 20555

Gentlemen:

Subject: **WNP-2, OPERATING LICENSE NPF-21,
RESPONSE TO NRC INSPECTION REPORT 50-397/97-13,
ADDITIONAL INFORMATION**

References: 1) Letter GO2-98-051, dated March 10, 1998, PR Bemis (SS) to NRC,
"Response to Apparent Violations, NRC Inspection Report 50-397/97-13"
2) Letter GO2-98-057, dated March 19, 1998, PR Bemis (SS) to NRC,
"Response to NRC Inspection Report 50-397/96-22, Supplemental
Information"

In Reference 1) the Supply System informed the NRC that the following corrective actions will be taken to avoid further violations:

- 1) A thorough review of other safety evaluations and associated changes to the facility since initial startup is nearly complete. This review is being performed to determine if the inappropriate use of generic guidance may have occurred, thereby resulting in the need for a license amendment.
- 2) Plant procedure PPM 1.3.43, Licensing Basis Impact Determinations, will be revised to clarify guidance for use and interpretation of generic documents applicable to WNP-2.
- 3) Lessons learned from this apparent violation will be provided as feedback training to 10 CFR 50.59 safety evaluation preparers and reviewers, as well as the Plant Operations Committee and the Corporate Nuclear Safety Review Board.

As noted in Reference 2, the first corrective action was completed on March 16, 1998. The second and third corrective actions noted above are expected to be completed by April 30, 1998.

9804010213 980323
PDR ADOCK 05000397
G PDR

Teal

**RESPONSE TO NRC INSPECTION REPORT 50-397/97-13,
ADDITIONAL INFORMATION**

Page 2

In addition, the Supply System informed the NRC in Reference 1) that:

“All pertinent RCIC components have been upgraded as necessary, with the exception of two rupture disks...”

The pertinent Reactor Core Isolation Cooling (RCIC) components referenced above were upgraded by January 8, 1998.

Should you have any questions or desire additional information regarding this matter, please call me or Mr. PJ Inserra at (509) 377-4147.

Respectfully,



DW Coleman
Acting Manager, Regulatory Affairs
Mail Drop PE20

cc: EW Merschoff - NRC RIV
KE Perkins, Jr. - NRC RIV, Walnut Creek Field Office
C Poslusny, Jr. - NRR
NRC Sr. Resident Inspector - 927N
DL Williams - BPA/399
PD Robinson - Winston & Strawn
TF Stetka - NRC RIV

