## CATEGORY 3

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR:9710220270 DOC.DATE: 97/10/17 NOTARIZED: NO DOCKET #
FACIL:50-328 Sequoyah Nuclear Plant, Unit 2, Tennessee Valley Auth 05000328
AUTH.NAME AUTHOR AFFILIATION
LESSER,M. Region 2 (Post 820201)
RECIP.NAME RECIPIENT AFFILIATION

SUBJECT: PNO-II-97-057:on 971017, discovered 12 of 14 instrument cables damaged in Unit 2 containment electrical penetration.
Sequoyah Unit 2 in outage & all fuel removed from reactor vessel.Licensee continues to investigate event.

DISTRIBUTION CODE: 1E34F COPIES RECEIVED:LTR OENCL SIZE: TITLE: 50 Docket & Vendors PNO/Non-Routine Event/Safeguards Event (PN)

NOTES:

	RECIPIENT	COPIES	RECIPIENT	COPIES
	ID CODE/NAME	· LTTR ENCL	ID CODE/NAME	LTTR ENCL
INTERNAL:	ACRS NRR/DISP/PIPB NUDOCS FULL TXT RES/DET/EIB RES/DRA/DEPY RES/DST DEPY RGN2 FILE 01		PILE CENTER NRR/DRPM/PERB OE DIR RES/DRA RES/DST RES/RPHEB	
EXTERNAL:	LITCO BRYCE, J H NRC PDR	1	NOAC	1

NOTE TO ALL "RIDS" RECIPIENTS: PLEASE HELP US TO REDUCE WASTE. TO HAVE YOUR NAME OR ORGANIZATION REMOVED FROM DISTRIBUTION LISTS OR REDUCE THE NUMBER OF COPIES RECEIVED BY YOU OR YOUR ORGANIZATION, CONTACT THE DOCUMENT CONTROL DESK (DCD) ON EXTENSION 415-2083

0

**ENCL** 

E

G

0

R

· 1.

D

U

E

N

T

October 17, 1997

-1--

## PRELIMINARY NOTIFICATION OF EVENT OR UNUSUAL OCCURRENCE PNO-II-97-057

This preliminary notification constitutes EARLY notice of events of POSSIBLE safety or public interest significance. The information is as initially received without verification or evaluation, and is basically all that is known by Region II staff in Atlanta, Georgia on this date.

Facility
Tennessee Valley Authority
Sequoyah 2
Soddy-Daisy, Tennessee
Dockets: 50-328

Licensee Emergency Classification
Notification of Unusual Event
Alert
Site Area Emergency
General Emergency
X Not Applicable

Subject: EQUIPMENT DAMAGE

At 11:00 a.m., October 17, 1997, Sequoyah Nuclear Plant reported to the NRC that they had discovered 12 of 14 instrument cables damaged in a Unit 2 Containment electrical penetration. Sequoyah Unit 2 is in an outage, and all fuel has been removed from the Reactor Vessel. The penetration was being replaced, and work had proceeded to the point that the penetration was being re-wired. The licensee continues to investigate the event and has taken compensatory measures.

TVA is prepared to respond to press inquires.

Region II is following licensee activities in response to this event.

The State of Tennessee has been informed.

This information is current as of 3:00 p.m., October 17, 1997.

Contact: MARK LESSER (404)562-4560

1831/ 100-

9710220270 971017 PDR I&E