NRC FORM 591M PART 1 (4-2008)	U.S. NUCLEAR REGULATORY COMMISSION				
10 CFR 2.201 SAFETY INS	SPECTION REPORT	AND COMPLIANCE	NSPECTIO	N	
1. LICENSEE/LOCATION INSPECTED:		2. NRC/REGIONAL OFFICE			
Spokane Washington Hospital Company MHS dba Deaconess Hospital 980 West Ironwood Drive, Suite 204 Coeur d'Alene, Idaho REPORT NO.: 030-38485/2017-001		U.S. Nuclear Regulatory Commission Region IV, 1600 East Lamar Blvd Arlington, Texas 76011-4511			
000-30403/20	000-00400/2017-001				
3. DOCKET NUMBER	4. LICENSE NUMBER			INSPECTION	
030-38485	46-29432-01			August 24, 2017	
The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows:    X					
Licensee's	Statement of Corre	ctive Actions for Item	4, above.		
I hereby state that, within 30 days, the actions corrective actions is made in accordance with the date when full compliance will be achieved). I  Title Printed Na	e requirements of 10 CFR understand that no furthe	2.201 (corrective steps alrea	dv taken, corre	ective steps which will be taken.	
LICENSEE'S REPRESENTATIVE					
NRC INSPECTOR Jason Dykert, Hea	llth Physicist	For Saket		8-31-2017	
BRANCH CHIEF  NRC FORM 591M PART 1	mpheli 9	wian H. Keny	oher "	9/11/17	
Non-Public Sensitive - Sec	curity-Related	x	Public	X Non-Sensitive	

## Dykert, Jason

From:

Dykert, Jason

Sent:

Thursday, August 31, 2017 12:46 PM

To:

'Smith, Andrew B'

Subject:

NRC inspection report 2017-001

**Attachments:** 

2017-001.pdf

Andrew, here is the inspection report as we discussed today. Please let me know if you have any questions,

## **Thanks**

Jason C Dykert Health Physicist, Inspection Branch US NRC, Region IV (817) 200 - 1427

