

ACCELERATED DISTRIBUTION DEMONSTRATION SYSTEM

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 8712170046 DOC. DATE: 87/12/14 NOTARIZED: NO DOCKET #
 FACIL: STN-50-528 Palo Verde Nuclear Station, Unit 1, Arizona Public 05000528
 AUTH. NAME AUTHOR AFFILIATION
 HAYNES, J.G. Arizona Nuclear Power Project (formerly Arizona Public Serv
 RECIP. NAME RECIPIENT AFFILIATION
 Document Control Branch (Document Control Desk)

SUBJECT: Special Rept 1-SR-87-025: on 871205, steam generator tubes
 plugged as result of inservice insp.

DISTRIBUTION CODE: IE22D COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 2 R
 TITLE: 50.73 Licensee Event Report (LER), Incident Rpt, etc. I


NOTES: Standardized plant. 05000528 D

	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL	
	PD5 LA	1 1	PD5 PD	1 1	/
	LICITRA, E	1 1	DAVIS, M	1 1	
INTERNAL:	ACRS MICHELSON	1 1	ACRS MOELLER	2 2	A
	AEOD/DOA	1 1	AEOD/DSP/NAS	1 1	
	AEOD/DSP/ROAB	2 2	AEOD/DSP/TPAB	1 1	D
	ARM/DCTS/DAB	1 1	DEDRO	1 1	
	NRR/DEST/ADS	1 0	NRR/DEST/CEB	1 1	D
	NRR/DEST/ELB	1 1	NRR/DEST/ICSB	1 1	
	NRR/DEST/MEB	1 1	NRR/DEST/MTB	1 1	S
	NRR/DEST/PSB	1 1	NRR/DEST/RSB	1 1	
	NRR/DEST/SGB	1 1	NRR/DLPQ/HFB	1 1	
	NRR/DLPQ/QAB	1 1	NRR/DOEA/EAB	1 1	
	NRR/DREP/RAB	1 1	NRR/DREP/RPB	2 2	
	NRR/DRIS/SIB	1 1	NRR/PMAS/ILRB	1 1	
	REG FILE 02	1 1	RES DEPY GI	1 1	
	RES TELFORD, J	1 1	RES/DE/EIB	1 1	
	RGN5 FILE 01	1 1			
EXTERNAL:	EG&G GROH, M	5 5	FORD BLDG HOY, A	1 1	
	H ST LOBBY WARD	1 1	LPDR	1 1	
	NRC PDR	1 1	NSIC HARRIS, J	1 1	
	NSIC MAYS, G	1 1			R

NOTES: 1 1 I

add NRR/DEST/ADE D

TOTAL NUMBER OF COPIES REQUIRED: LTR ⁴⁹ 48 ENCL 47 S





Arizona Nuclear Power Project

P.O. BOX 52034 • PHOENIX, ARIZONA 85072-2034

192-00324-JGH/TRB/DAJ
December 14, 1987

U.S. Nuclear Regulatory Commission
NRC Document Control Desk
Washington, D.C. 20555

Dear Sirs:

Subject: Palo Verde Nuclear Generating Station (PVNGS)
Unit 1
Docket No. STN 50-528 (License No. NPF-51)
Special Report 1-SR-87-025
File: 87-020-404

Attached please find Special Report 1-SR-87-025 prepared and submitted pursuant to Technical Specification 3.4.4 and 6.9.2. This report discusses Steam Generator tubes plugged as a result of an Inservice Inspection.

If you have any questions, please contact J. E. Malik, (Acting) Compliance Lead at (602) 393-3527.

Very truly yours,

J. G. Haynes
Vice President
Nuclear Production

JGH/JEM/kj


Attachment

cc: O. M. DeMichele (all w/a)
E. E. Van Brunt, Jr.
J. B. Martin
J. R. Ball
E. A. Licitra
A. C. Gehr
INPO Records Center

Add: NRR/DEST/ADE 1 ⁴⁴

1E22
11

8712170046 871214
PDR ADOCK 05000528
S DCD



PALO VERDE NUCLEAR GENERATING STATION

STEAM GENERATOR TUBE PLUGGING

License No. NPF-41

Docket No. STN-528

Special Report 1-SR-87-025

This special report is required by Palo Verde Unit 1 Technical Specification 3.4.4 section 4.4.4.5 REPORTS a, within 15 days following the completion of each inservice inspection of steam generator tubes.

On December 5, 1987, Palo Verde Unit 1 was in Mode 5 (COLD SHUTDOWN), when an inservice inspection of both steam generators was completed. The inspection resulted in the plugging of 11 tubes in steam generator number 1 and 1 tube in steam generator number 2.

The complete results of the steam generator tube inservice inspection will be submitted to the Commission in a Special Report within 12 months following completion of the inspection as required by Technical Specification section 4.4.4.5 REPORTS b.

