REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ESSION NBR:8909130123 DOC.DATE: 89/08/29 NOTARIZED: NO DOCKET # FACIL:STN-50-528 Palo Verde Nuclear Station, Unit 1, Arizona Publi STN-50-529 Palo Verde Nuclear Station, Unit 2, Arizona Publi STN-50-530 Palo Verde Nuclear Station, Unit 3, Arizona Publi 05000528 05000529 05000530 AUTHOR AFFILIATION AUTH. NAME

CHAFFEE, A.E. Region 5, Ofc of the Director

RECIPIENT AFFILIATION RECIP: NAME

Arizona Public Service Co. (formerly Arizona Nuclear Power CONWAY, W.F.

SUBJECT: Forwards Insp Repts 50-528/89-30,50-529/89-30 & 50-530/89-30

on 890612-0806 & notice of violation.

DISTRIBUTION CODE: IE01D COPIES RECEIVED:LTR —ENCL — TITLE: General (50 Dkt)-Insp Rept/Notice of Violation Response

NOTES:

Standardized plant. Standardized plant. 05000528 05000529 05000530 K

D

D

D

S


R

	RECIPIENT ID CODE/NAME PD5 PD DAVIS,M.		COPIE LTTR 1 1	S ENCL 1	RECIPIENT ID CODE/NAME CHAN,T	COP: LTTR	IES ENCL 1		
INTERNAL:	ACRS AEOD/DEIIB		2 1	2 1	AEOD AEOD/TPAD	1	1	. •	
	DEDRO		1	1	LOIS, ERASMIA	1	1		
	NRR SHANKMAN,S NRR/DLPQ/PEB		1	1	NRR/DEST DIR NRR/DOEA DIR 11	1 1	1 1		
	NRR/DREP/EPB 1)	ī	ī	NRR/DREP/RPB 10	2	2		
	NRR/PMAS/ILRB1:		1	1	NUDOCS-ABSTRACT	1	1		
	OE-LIEBERMAN, J		1	1	OGC/HDS1	1	1		
	REG FILE 0:		1	1	RES MORISSEAU, D	1	1		
EXTERNAL:	LPDR NSIC		1	1	NRC PDR	1	1		
NOTES:			1	1			•	,	

NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK, ROOM P1-37 (EXT. 20079) TO ELIMINATE YOUR NAME FROM DISTRIBUTION LISTS FOR DOCUMENTS YOU DON'T NEED!

TAL NUMBER OF COPIES REQUIRED: LTTR ENCL ***28********



Docket Numbers 50-528 50-529 50-530

Arizona Nuclear Power Project P. O. Box 52034 Phoenix, Arizona 85072-2034

Attention:

Mr. W. F. Conway,

Executive Vice President, Nuclear

Gentlemen:

Subject: NRC Inspection of Palo Verde Units 1, 2 and 3

This refers to the inspection conducted by Messrs. T. Polich, D. Coe, C. Myers, and P. Qualls, on June 12 through August 6, 1989, of activities authorized by NRC License Nos. NPF-41, NPF-51 and NPF-74, and to the discussion of our findings held by the inspectors with members of the Arizona Nuclear Power Project staff at the conclusion of the inspection.

Areas examined during this inspection are described in the enclosed inspection report. Within these areas, the inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspectors.


Based on the results of this inspection, it appears that several of your activities were not conducted in full compliance with NRC requirements, as set forth in the Notice of Violation, enclosed herewith as Appendix A.

Paragraph 11 of the enclosed inspection report discusses a long standing problem with the operation of the Unit 2 pressurizer spray valves, which contributed to a safety injection actuation following the July 12, 1989 Unit 2 reactor trip. Our review determined that the problem with the spray valves has a lengthy documented history, however, the issue has only recently been raised to upper management's attention. As we have discussed with you during recent NRC/ANPP management meetings, we are concerned that other issues of long duration may exist which have not received an appropriate level of attention. We encourage you to take whatever actions are necessary to ensure that known plant problems are being promptly and completely acted on.

Following the July 12, 1987 reactor trip, portions of the non safety related main feedwater (MFW) system were inadvertently overpressurized. In discussions with you and your staff, we have frequently expressed the importance of stopping when faced with uncertainty, and the importance of conducting engineering work in a rigorous, documented, and controlled manner. Therefore we were disappointed to conclude that the actions taken by your engineering staff to evaluate the overpressurization condition were hurried, poorly documented initially, and based on erroneous assumptions. This is further discussed in paragraph 12 of the enclosed report.

The same of the sa

8909130123 890829 PDR ADOCK 05000528



Paragraph 14 of the enclosed inspection report discusses the setting of an Atmospheric Dump Valve nitrogen pressure regulator in accordance with verbal vendor instructions contrary to component technical manual requirements. This resulted in the improper setting and subsequent malfunction of the regulator. We are concerned about your lack of controls in the performance of safety-related maintenance on important plant components. In your response to the attached Notice of Violation, please discuss the specific quality controls you are implementing to preclude recurrence of the cited problem.

Your response to the enclosed Notice is to be submitted in accordance with the provisions of 10 CFR 2.201 as stated in Appendix A, Notice of Violation.

In accordance with 10 CFR 2.790(a), a copy of this letter and the enclosures will be placed in the NRC Public Document Room.

The response directed by this letter and the accompanying Notice are not subject to the clearance procedure of the Office of Management and Budget as required by the Paperwork Reduction Act of 1980, PL 96-511.

Should you have any questions concerning this inspection, we will be pleased to discuss them with you.

Sincerely,

Original Signed

A. E. Chaffee, Deputy Director


Division of Reactor Safety and Projects

Enclosure:

- 1. Appendix A Notice of Violation
- 2. Inspection Report Numbers 50-528/89-30, 50-529/89-30, and 50-530/89-30

cc w/enclosures:

- J. G. Haynes, Vice President, Nuclear Production
- W. F. Quinn, Manager, Licensing
- T. D. Shriver, Manager, Compliance
- B. Ballard, Director, Quality Assurance
- R. Fullmer, Manager, Quality Audits & Monitoring
- A. C. Gehr, Esq.
- Ms. L. Bernabei, GAP
- J. Brown, Arizona Corporation Commission



	bcc w/enc docket fi G. Cook B. Faulke J. Martin Resident Project I R. Nease,	le nberry Inspector		·			,
	bcc w/o e LFMB M. Smith N. Wester		·				
	REGION V/dot	20 27	DO	7		CD: aba	
	CMyers	PQualls 8/24/89	DCoe 8/24		「Polich 3/24/89	SRicha 8/2 <u>1</u> /8	aras Ro_
	8/24/89 . 67 / km	200 m	500	ر مولاً	SAP	6/25/	A CONTRACTOR OF THE PARTY OF TH
	REQUEST COPY]		COPY J REQUI			OPY REQUES	ST COPY]
(YES) / NO]	(ES) / 1	NO] (YES)	/ NO TY	<u>/E\$ / N</u>	O JYES)	/ NO]
	RZimmerman		ON to	T-15			
	8/ C/89 acc	•		20 (10c			
	REQUEST COPY			8/25/89_	_		
1	YES / NO T	_	. (DOW (NO)		
				207			-
	SEND TO PDR] (YÉS) / NO]		-				
	(ES) / NO]		-				

8/24/89 8/24/89

(10)

