

ACCELERATED DISTRIBUTION DEMONSTRATION SYSTEM

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 9107020400 DOC. DATE: 91/06/21 NOTARIZED: NO DOCKET #
FACIL: STN-50-528 Palo Verde Nuclear Station, Unit 1, Arizona Publi 05000528
STN-50-529 Palo Verde Nuclear Station, Unit 2, Arizona Publi 05000529
STN-50-530 Palo Verde Nuclear Station, Unit 3, Arizona Publi 05000530
AUTH. NAME AUTHORITY AFFILIATION
CONWAY, W.F. Arizona Public Service Co. (formerly Arizona Nuclear Power R
RECIP. NAME RECIPIENT AFFILIATION
Document Control Branch (Document Control Desk) I

SUBJECT: Documents closure of NRC Bulletin 89-001 & Suppl 1, "Failure of Westinghouse Steam Generator Tube Mechanical Plugs." Util D
removed 95 Westinghouse Inconel 600 tube plugs & replaced S
plugs w/Inconel 690 plugs during Unit 2 Cycle 3 outage.

DISTRIBUTION CODE: IE31D COPIES RECEIVED: LTR 1 ENCL 0 SIZE: 1 /
TITLE: Bulletin Response 89-01 re Failure of Westinghouse Steam Gen. Mech. T A

NOTES: STANDARDIZED PLANT 05000528
Standardized plant. 05000529 D
Standardized plant. 05000530 D


	RECIPIENT		COPIES		
	ID CODE/NAME	LTR	ENCL		
	PDS LA	1	1		
	TRAMMELL, C	1	1		
INTERNAL:	AEOD/DOA	1	1		
	NRR/DET/EMCB 9H	1	1		
	NRR/DOEA/OEAB11	1	1		
	NRR/DREP/PEPB9D	1	1		
	NRR/PMAS/ILRB12	1	1		
	RES/DSIR/EIB	1	1		
EXTERNAL:	NRC PDR	1	1		
NOTES:		1	1		

NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK,
ROOM P1-37 (EXT. 20079) TO ELIMINATE YOUR NAME FROM DISTRIBUTION
LISTS FOR DOCUMENTS YOU DON'T NEED!

TOTAL NUMBER OF COPIES REQUIRED: LTR 19 ENCL ~~19~~ 0

A01



Arizona Public Service Company

P.O. BOX 53999 • PHOENIX, ARIZONA 85072-3999

WILLIAM F. CONWAY
EXECUTIVE VICE PRESIDENT
NUCLEAR

161-04017-WFC/JMQ

June 21, 1991

Docket Nos. STN 50-528/529/530

U. S. Nuclear Regulatory Commission
Attn: Document Control Desk
Mail Station P1-37
Washington, D. C. 20555

Reference: Letter from W. F. Conway, APS (161-01990-WFC), to NRC Document Control Desk, dated June 2, 1989; Subject: "Response to Actions Requested of NRC Bulletin 89-01"

Dear Sirs:


Subject: Palo Verde Nuclear Generating Station (PVNGS)
Units 1, 2, and 3
NRC Bulletin 89-01, and Supplement 1 "Failure of Westinghouse Steam Generator Tube Mechanical Plugs"
File: 91-056-026

This letter documents Arizona Public Service Company's (APS') closure of NRC Bulletin 89-01, and Supplement 1 "Failure of Westinghouse Steam Generator Tube Mechanical Plugs," as requested by Mr. C. M. Trammell, NRC Project Manager.

In the referenced letter, APS responded to the bulletin and committed to remove or repair the tube plugs of the affected heat treat numbers during the Unit 2, Cycle 3 refueling outage. APS has removed the 95 Westinghouse Inconel 600 mechanical tube plugs that were identified in Table 1 of the referenced letter, and replaced them with Inconel 690 mechanical tube plugs during the Unit 2, Cycle 3 refueling outage.

If you should have any questions, please contact Michael E. Powell of my staff at (602) 340-4981.

Sincerely,



WFC/JMQ/sad

cc: J. B. Martin
D. H. Coe
A. C. Gehr
A. H. Gutterman

9107020400 910621
PDR ADOCK 05000528
Q PDR

IE31
110

