

NOTICE OF VIOLATION

Arizona Public Service Company
P.O. Box 53999, Station 9012
Phoenix, Arizona 85072-3999

Docket Nos. 50-528
License Nos. NPF-41

During an NRC inspection conducted from June 3 to June 12, 1991, a violation of NRC requirements was identified. In accordance with the "General Statement of Policy and Procedure for the NRC Enforcement Actions," 10 CFR Part 2, Appendix C(1991), the violation is listed below:

NPF-41 License Condition C (7), Fire Protection Program, requires, in part, that the licensee implement and maintain in effect all provisions of the approved fire protection program as described in the Final Safety Analysis Report for the facility.

Contrary to the above, on June 6, 1991, fire barrier material, required by the approved fire protection program, was missing from an HVAC spool piece for a damper in the Unit 1 "B" auxiliary feedwater pump room. This material had been removed during October 1990 in accordance with Work Request 778204 to permit inspection of the damper.

This is a Severity Level IV Violation, Supplement I.

Pursuant to the provisions of 10 CFR.2.201, Arizona Public Service Company System is hereby required to submit a written statement or explanation to the U.S. Nuclear Regulatory Commission, ATTN: Document Control Desk, Washington, D.C. 20555, with a copy to the Regional Administrator, Region V, and a copy to the NRC Resident Inspector, within 30 days of the date of the letter transmitting this Notice. This reply should be clearly marked as a "Reply to a Notice of Violation" and should include for each violation: (1) the reason for the violation if admitted (2) the corrective steps that will be taken and the results achieved, (3) the corrective steps that will be taken to avoid further violations, and (4) the date when full compliance will be achieved. If an adequate reply is not received within the time specified in this Notice, an order may be issued to show cause why the license should not be modified, suspended, or revoked or why such other action as may be proper should not be taken. Consideration may be given to extending the response time for good cause shown.

Dated at Walnut Creek, California
this 16 day of July 1991

