(NUDOCS OFFSITE FACILITY) REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR:9407220022 DOC.DATE: 94/07/18 NOTARIZED: NO DOCKET # ACIL:STN-50-528 Palo Verde Nuclear Station, Unit 1, Arizona Publi 05000528 STN-50-529 Palo Verde Nuclear Station, Unit 2, Arizona Publi 05000529 STN-50-530 Palo Verde Nuclear Station, Unit 3, Arizona Publi 05000530

AUTH. NAME AUTHOR AFFILIATION

Region 4 (Post 820201)

· BEACH, A.B. RECIPIENT AFFILIATION RECIP.NAME

Arizona Public Service Co. (formerly Arizona Nuclear Power STEWART, W.L.

SUBJECT: Forwards insp repts 50-528/94-23 & 50-529/94-23 & 50-530/94-23 on 940528-0603 & notice of vilolation. Violations of NRC concern because violations highlight need to reduce personnel errors.

DISTRIBUTION CODE: IE01D COPIES RECEIVED:LTR ENCL SIZE: TITLE: General (50 Dkt)-Insp Rept/Notice of Violation Response

NOTES:STANDARDIZED PLANT

Standardized plant. Standardized plant. 05000528 05000529 05000530

	RECIPIENT ID CODE/NAME PDIV-3 PD TRAN,L	COPII LTTR 1 1	ES ENCL 1 1	RECIPIENT ID CODE/NAME HOLIAN, B	COP LTTR 1	IES ENCL 1
TERNAL:	ACRS AEOD/DSP/ROAB AEOD/TTC NRR/DORS/OEAB NRR/PMAS/IRCB-E OE_DIR REG_FILE 02 RGN4 FILE 01	2 1 1 1 1 1	2 1 1 1 1 1	AEOD/DEIB AEOD/DSP/TPAB DEDRO NRR/DRCH/HHFB NUDOCS-ABSTRACT OGC/HDS2 RES/HFB	1 1 1 1 1	1 1 1 1 1 1 1
EXTERNAL:	EG&G/BRYCE, J.H. NSIC	1	1	NRC PDR	1	1

NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK, ROOM P1-37 (EXT. 504-2083) TO ELIMINATE YOUR NAME FROM DISTRIBUTION LISTS FOR DOCUMENTS YOU DON'T NEED!

 UNITED STATES



NUCLEAR REGULATORY COMMISSION

REGION IV

611 RYAN PLAZA DRIVE, SUITE 400 ARLINGTON, JEXAS 76011-8064

JUL 18 1994

Dockets: 50-528

50-529

50-530

Licenses: NPF-41

NPF-51 NPF-74

Arizona Public Service Company

ATTN: William L. Stewart

Executive Vice President, Nuclear

P.O. Box 53999

Phoenix, Arizona 85072-3999

SUBJECT: NRC SPECIAL INSPECTION REPORT 50-528/94-23; 50-529/94-23;

50-530/94-23 (NOTICE OF VIOLATION)

This refers to the special inspection conducted by H. Wong and others, of this office and the Office of Nuclear Reactor Regulation, on May 28 through June 3, 1994. The inspection included a review of activities authorized for your Palo Verde Nuclear Generating Station, Units 1, 2, and 3, facility. At the conclusion of the inspection, the findings were discussed with J. Levine and those members of your staff identified in the enclosed report.

Areas examined during the inspection are identified in the report. The special inspection reviewed the circumstances of the Unit 2 reactor trip of May 28, 1994, and assessed the adequacy of the Arizona Public Service Company's response to the event. Within these areas, the inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observation of activities in progress. The purpose of the inspection was to determine whether activities authorized by the license were conducted safely and in accordance with NRC requirements.

Based on the results of this inspection, certain licensed activities appeared to be in violation of NRC requirements, as specified in the enclosed Notice of Violation (Notice). The violation and the issues identified in the event are of concern because they highlight a need to: (1) reduce personnel errors, (2) improve communications between maintenance and operations personnel, (3) maintain an effective questioning attitude, (4) maintain a "big picture" view when responding to plant conditions which are not understood, and (5) carefully assess the "re-engineering" changes made to streamline your work processes to assure that barriers important to assuring safety are not removed.

We found your review of this event to be thorough and a high level of management involvement was evident. However, from this event, we are particularly concerned regarding the mindsets of the instrument and control

9407220022 940718 PDR ADDCK 05000528 Q PDR 1801

technician involved in the work and the operators responding to the rising containment sump level. The instrument and control technician had a mindset regarding the appropriate train of the containment spray system on which to work. The operators had a mindset that the valve in the correct train of the containment spray system had been closed with power removed and could not be causing the sump level rise. These mindsets contributed significantly to causing this event. Action is needed to assure that additional mindsets do not cause other, perhaps more significant, events. Additionally, program changes made to increase work efficiency through your "re-engineering" efforts must also balance the need to assure that the sufficient safeguards are in place for appropriate control over the new processes.

You are required to respond to this letter and should follow the instructions specified in the enclosed Notice when preparing your response. In your response, you should document the specific actions taken and any additional actions you plan to prevent recurrence. After reviewing your response to this Notice, including your proposed corrective actions and the results of future inspections, the NRC will determine whether further NRC enforcement action is necessary to ensure compliance with NRC regulatory requirements.

In accordance with 10 CFR 2.790 of the NRC's "Rules of Practice," a copy of this letter and its enclosures will be placed in the NRC Public Document Room.

The responses directed by this letter and the enclosed Notice are not subject to the clearance procedures of the Office of Management and Budget as required by the Paperwork Reduction Act of 1980, Pub. L. No. 96.511.

Should you have any questions concerning this inspection, we will be pleased to discuss them with you.

Sincerely,


fw A. Bill Beach, Director
Division of Reactor Projects

Enclosures:

Appendix A - Notice of Violation
 Appendix B - NRC Inspection Report

50-528/94-23; 50-529/94-23; 50-530/94-23

cc w/enclosures: Arizona Corporation Commission ATTN: Mr. Steve Olea 1200 W. Washington Street Phoenix, Arizona 85007



Southern California Edison Company ATTN: T. E. Oubre, Esq. P.O. Box 800 Rosemead, California 91770

ABB Combustion Engineering Nuclear Power ATTN: Charles B. Brinkman, Manager Washington Nuclear Operations 12300 Twinbrook Parkway, Suite 330 Rockville, Maryland 20852

Arizona Radiation Regulatory Agency ATTN: Aubrey V. Godwin, Director 4814 South 40 Street Phoenix, Arizona 85040


Maricopa County Board of Supervisors ATTN: Chairman 111 South Third Avenue Phoenix, Arizona 85003

Newman & Holtzinger, P.C. ATTN: Jack R. Newman, Esq. 1615 L Street, N.W., Suite 1000 Washington, D.C. 20036

Palo Verde Services
ATTN: Curtis Hoskins, Executive
Vice President and
Chief Operating Officer
2025 N. 3rd Street, Suite 220
Phoenix, Arizona 85004

Akin, Gump, Strauss, Hauer and Feld El Paso Electric Company ATTN: Roy P. Lessey, Jr., Esq. 1333 New Hampshire Avenue, Suite 400 Washington, D.C. 20036

Arizona Public Service Company ATTN: Angela K. Krainik, Manager Nuclear Licensing P.O. Box 52034 Phoenix, Arizona 85072-2034



E-Mail report to D. Sullivan (DJS)

bcc to DMB (IE01)

bcc distrib. by RIV:

L. J. Callan

Resident Inspector

MIS System

DRSS-FIPB Branch Chief (DRP/F, WCFO)

Senior Project Inspector (DRP/F, WCFO)

Branch Chief (DRP/TSS)

RIV File Leah Tremper, OC/LFDCB, MS: MNBB 4503


P. Eng, NRR

F. Burrows, NRR

A. MacDougall, (PV Resident Inspector Office)
J. Ganiere, (PV Resident Inspector Office)

re			
RIV:C:DRP/F*	D:WCFO*	D:DRP	
HJWong	KEPerkins	FABBeach DUL	
7/12/94	7/12/94	7/16/94	

^{*}previously concurred



E-Mail report to D. Sullivan (DJS)

bcc to DMB (IEO1)

bcc distrib. by RIV:

L. J. Callan

DRSS-FIPB

RIV File

Resident Inspector

MIS System

Branch Chief (DRP/F, WCFO)

Senior Project Inspector (DRP/F, WCFO)

Branch Chief (DRP/TSS)

Leah Tremper, OC/LFDCB, MS: MNBB 4503

P. Eng, NRR

F. Burrows, NRR

A. MacDougall, (PV Resident Inspector Office)
J. Ganiere, (PV Resident Inspector Office)

RIV:C:DRP/F*	D:WCFO*	D:DRP	·	
HJWong	KEPerkins	FABBeach DUL	-	
7/12/94	7/12/94	7/16/94	·	

^{*}previously concurred

