

CATEGORY 1

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR:9902030246 DOC.DATE: 99/01/15 NOTARIZED: NO DOCKET #
 FACIL:STN-50-528 Palo Verde Nuclear Station, Unit 1, Arizona Publi .05000528
 AUTH.NAME AUTHOR AFFILIATION
 OVERBECK,G.R. Arizona Public Service Co. (formerly Arizona Nuclear Power
 RECIP.NAME RECIPIENT AFFILIATION
 Records Management Branch (Document Control Desk)

SUBJECT: Forwards LER 96-003-00 prepared & submitted pursuant to
 10CFR50.73.LER reports TS violation involving nuclear power
 channel calibrations, due to precedural deficiency.

DISTRIBUTION CODE: IE22T COPIES RECEIVED:LTR 1 ENCL 1 SIZE: 1+6
 TITLE: 50.73/50.9 Licensee Event Report (LER), Incident Rpt, etc.

NOTES:STANDARDIZED PLANT

05000528

	RECIPIENT		COPIES		RECIPIENT		COPIES	
	ID	CODE/NAME	LTR	ENCL	ID	CODE/NAME	LTR	ENCL
	PD4-2	PD	1	1	FIELDS,M		1	1
INTERNAL:	ACRS		1	1	AEOD/SPD/RAB		2	2
	AEOD/SPD/RRAB		1	1	<u>FILE CENTER</u>		1	1
	NRR/DE/ECGB		1	1	NRR/DE/EELB		1	1
	NRR/DE/EMEB		1	1	NRR/DRCH/HICB		1	1
	NRR/DRCH/HOHB		1	1	NRR/DRCH/HQMB		1	1
	NRR/DRPM/PECB		1	1	NRR/DSSA/SPLB		1	1
	RES/DET/EIB		1	1	RGN4 FILE 01		1	1
EXTERNAL:	L ST LOBBY WARD		1	1	LITCO BRYCE,J H		1	1
	NOAC POORE,W.		1	1	NOAC QUEENER,DS		1	1
	NRC PDR		1	1	NUDOCS FULL TXT		1	1

NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE. TO HAVE YOUR NAME OR ORGANIZATION REMOVED FROM DISTRIBUTION LISTS OR REDUCE THE NUMBER OF COPIES RECEIVED BY YOU OR YOUR ORGANIZATION, CONTACT THE DOCUMENT CONTROL DESK (DCD) ON EXTENSION 415-2083

FULL TEXT CONVERSION REQUIRED
 TOTAL NUMBER OF COPIES REQUIRED: LTR 23 ENCL 23

AD4



Palo Verde Nuclear
Generating Station

Gregg R. Overbeck
Vice President
Nuclear Production

TEL 602/393-5148
FAX 602/393-6077

Mail Station 7602
P.O. Box 52034
Phoenix, AZ 85072-2034

192-01038-GRO/DGM/REB
January 15, 1999

U. S. Nuclear Regulatory Commission
ATTN: Document Control Desk
Mail Station P1-37
Washington, D.C. 20555-0001

Dear Sirs:

**Subject: Palo Verde Nuclear Generating Station (PVNGS)
Units 1 and 2
Docket No. STN 50-528/529
License No. NPF-41/51
Licensee Event Report 96-008-00**

Attached please find Licensee Event Report (LER) 96-008-00 prepared and submitted pursuant to 10CFR50.73. This LER reports a Technical Specification violation involving nuclear power channel calibrations due to a procedural deficiency. In accordance with 10CFR50.73(d) and 50.4, a copy of this LER is being forwarded to the Regional Administrator, NRC Region IV and the Resident Inspector. If you have any questions, please contact Daniel G. Marks, Section Leader, Nuclear Regulatory Affairs, at (602) 393-6492.

The LER contains a commitment to correct the Power Calibration procedure prior to Physics Testing in Unit 2 following its upcoming outage. 1/1

Sincerely,

GRO/DGM/REB/rjh

Attachment

030012

cc: E. W. Merschoff (all with attachment)
M. B. Fields
J. H. Moorman
INPO Records Center
Licensee Event Report 1-96-008-00

9902030246 990115
PDR ADOCK 05000528
S PDR

