

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 7902080.173 DOC. DATE: 79/01/23 NOTARIZED: NO DOCKET #
 FACIL: 50-315 Donald C. Cook Nuclear Power Plant, Unit 1, Indiana & 05000315
 AUTH. NAME: SHALLER, D.V. AUTHOR AFFILIATION: Indiana & Michigan Power Co.
 RECIP. NAME: KEPPLER, J.G. RECIPIENT AFFILIATION: Region 3, Chicago, Office of the Director

SUBJECT: Forwards "Special Rept SI-11" re 780114 Safety injection actuation occurrence resulting from operator error. Major components & functions were reviewed & found to be in good order. W/2 previous repts having new rept numbers.

DISTRIBUTION CODE: A002S. COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 7
 TITLE: INCIDENT REPORTS

NOTES: FAE - 3 cys All Matl.

ACTION:	RECIPIENT	COPIES		RECIPIENT	COPIES	
	ID CODE/NAME	LTR	ENCL	ID CODE/NAME	LTR	ENCL
	05 BC DRB#1	4	4			
INTERNAL:	01 <u>REG FILE</u>	1	1	02 NRC PDR	1	1
	09 I&E	2	2	11 MPA	3	3
	14 TA/EDO	1	1	15 NOVAK/KNIEL	1	1
	16 EEB	1	1	17 AD FOR ENGR	1	1
	18 PLANT SYS BR	1	1	19 I&C SYS BR	1	1
	20 AD PLANT SYS	1	1	21 AD SYS/PROJ	1	1
	22 REAC SAFT BR	1	1	23 ENGR BR	1	1
	24 KREGER	1	1	25 PWR SYS BR	1	1
	26 AD/SITE ANAL	1	1	27 OPERA LIC BR	1	1
	28 ACIDENT ANLYS	1	1	E JORDAN/IE	1	1
EXTERNAL:	03 LPDR	1	1	04 NSIC	1	1
	29 ACRS	16	16			

FEB 9 1979
 1979

MA 4
 60

TOTAL NUMBER OF COPIES REQUIRED: LTR 45 ENCL 45

THE UNIVERSITY OF CHICAGO
DEPARTMENT OF CHEMISTRY
5800 S. UNIVERSITY AVENUE
CHICAGO, ILLINOIS 60637

RECEIVED
JAN 15 1964

FROM
DR. J. H. GOLDSTEIN

TO
DR. R. M. MAYER

RE
NMR SPECTRA OF
POLYMER SOLUTIONS

ATTENTION
DR. R. M. MAYER

DEPARTMENT OF CHEMISTRY
UNIVERSITY OF CHICAGO

5800 S. UNIVERSITY AVENUE
CHICAGO, ILLINOIS 60637

TELEPHONE 373-3300
TELETYPE 373-3300

FACSIMILE 373-3300

POST OFFICE BOX 37073
CHICAGO, ILLINOIS 60637

015c



INDIANA & MICHIGAN POWER COMPANY

DONALD C. COOK NUCLEAR PLANT
P.O. Box 458, Bridgman, Michigan 49106

January 23, 1979

Mr. J. G. Keppler, Regional Director
Office of Inspection and Enforcement
United States Nuclear Regulatory Commission
Region III
799 Roosevelt Road
Glen Ellyn, IL 60137

Operating License DPR-58
Docket No. 50-315
Special Report: SI-11

Dear Mr. Keppler:

The purpose of this letter is to forward you the attached Special Reports as required by Appendix A Technical Specification 3.5.2 Emergency Core Cooling Subsystems.

Special Report SI-11 should have been submitted prior to April 14, 1978.

Our letter to you of November 7, 1978 also reported two instances of failure to submit a Special Report within 90 days. At that time we established a tickler system for Special Reports but did not attempt to backfit all internal reports to determine if any other reports had been missed. Resident Inspector Mr. K. R. Baker, in his review of internal reports, discovered that we had failed to submit the attached report.

We have now reviewed all internal reports and determined there are no other missing Special Reports required. This review also revealed we had submitted two Special Reports numbered SI-08. To correct this discrepancy, we are enclosing renumbered reports. SI-08 for the safety injection actuation which occurred on September 2, 1977 has been changed to SI-09. SI-09 for the safety injection actuation which occurred on September 4, 1977 has been renumbered SI-10.

Sincerely,

D. V. Shaller
Plant Manager

REGULATORY DOCKET FILE COPY

A002
SI-11

- | | | | |
|-----------------|--------------------|----------------------|----------------|
| cc: J. E. Dolan | R. J. Vollen BPI | P. W. Steketee, Esq. | PNSRC |
| R. W. Jurgensen | K. R. Baker RO:III | R. Walsh, Esq. | J. F. Stietzel |
| R. F. Kroeger | R. C. Callen MPSC | M. H. Judkis | R. S. Keith |

7902080173

13 1979

11-11-11

11-11-11