

American Electric Power Service
 Corporation
 Indiana and Michigan Power Company

- 2 -

MAY 8 1979

In accordance with Section 2.790 of the NRC's "Rules of Practice," Part 2, Title 10, Code of Federal Regulations, a copy of this letter, the enclosures, and your response to this letter will be placed in the NRC's Public Document Room, except as follows. If the enclosures contain information that you or your contractors believe to be proprietary, you must apply in writing to this office, within twenty days of your receipt of this letter, to withhold such information from public disclosure. The application must include a full statement of the reasons for which the information is considered proprietary, and should be prepared so that proprietary information identified in the application is contained in an enclosure to the application.

We will gladly discuss any questions you have concerning this inspection.

Sincerely,

R. F. Heishman, Chief
 Reactor Operations and
 Nuclear Support Branch

Enclosures:

1. Appendix A, Notice of Violation
2. IE Inspection Rpts
 No. 50-315/79-05;
 and 50-316/79-05

cc w/encs:

Mr. D. V. Shaller, Plant Manager
 Central Files
 Reproduction Unit NRC 20b
 PDR
 Local PDR
 NSIC

2307270399

OFFICE	RIII <i>R.F.H.</i>	RIII <i>R.F.H.</i>	RIII <i>R.F.H.</i>			
SURNAME	Masse/gc	Warnick	Heishman			
DATE	5/2/79		5/4/79			

20251028

2025

Appendix A

NOTICE OF VIOLATION

American Electric Power
Service Corporation
Indiana and Michigan
Power Company

Docket No. 50-315; 50-316

Based on the inspection conducted on March 5-9, 12-16, 19-23, 26-31 and April 1-6, 1979, certain of your activities were in noncompliance with NRC requirements, as noted below. Items 1 and 2 are infractions.

Item 1: (Both Units) Technical Specification 6.8.1 requires implementation of written procedures. Procedures 12-OHP-4030 STP.035 "Locked or Sealed Valve Position Logging" requires certain valves to be logged as to position changes.

Contrary to the above, the position of valve 1-WD-230-7 was changed on March 28, 1979 without being logged as required.

Item 2: (Unit 1 only) Technical Specification 6.8.1 requires implementation of written procedures. Temporary change number 3 to 1-OHP 4021.032.001 "Starting, Loading, Paralleling and Shutting Down Diesel-Generators" requires an entry into the Jumper/Lifted Lead Log when pulling and replacing field flash fuses for diesel-generator starts.

Contrary to the above, 1 CD diesel-generator was started on March 26, 1979 with no corresponding log entry.

7907270399

5003104 21