

UNITED STATES
NUCLEAR REGULATORY COMMISSION
REGION III
799 ROOSEVELT ROAD
GLEN ELLYN, ILLINOIS 60137

CENTRAL FILES

January 23, 1981

Docket No. 50-315
Docket No. 50-316

American Electric Power Service
Corporation
Indiana and Michigan Power Company
ATTN: Mr. John E. Dolan
Vice Chairman
Engineering
2 Broadway
New York, NY 10004



Gentlemen:


This refers to the routine inspection conducted by K. R. Baker, J. M. Peschel, M. M. Holzmer, K. A. Connaughton of this office on November 17-21, 1980 and January 13, 1981, of activities at Donald C. Cook Nuclear Plant, Units 1 and 2 authorized by NRC Operations Licenses No. DPR-58 and No. DPR-74 and to the discussion of our findings with Mr. Shaller and others of your staff at the conclusion of the inspection.

The enclosed copy of our inspection report identifies areas examined during the inspection. Within these areas, the inspection consisted of a selective examination of procedures and representative records, observations, and interviews with personnel.

During this inspection, certain of your activities appeared to be in non-compliance with NRC requirements, as described in the enclosed Appendix A, and a written response is required.

8103130104

Q



American Electric Power
Service Corporation

- 2 -

January 23, 1981

We will gladly discuss any questions you have concerning this inspection.

Sincerely,

R. F. Heishman, Chief
Reactor Operations and
Nuclear Support Branch

Enclosures:

1. Appendix A, Notice
of Violation
2. IE Inspection Reports
No. 50-315/80-20 and
No. 50-316/80-16

cc w/encls:

D. V. Shaller, Plant
Manager
Central Files
Reproduction Unit NRC 20b
AEOD
Resident Inspector, RIII
PDR
Local PDR
NSIC
TIC
Ronald Callen, Michigan
Public Service Commission

RIII

Peschel/so
12/15/80

[Signature]
1/22/81

RIII

Holzmer

[Signature]
1/22/81

RIII

Connaughton

[Signature]
1/22/81

RIII

Baker

[Signature]
1/21/81

[Signature]
RIII
Baker
1-21/81
Heishman
1/22/81