

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 8205180270 DOC. DATE: 82/05/13 NOTARIZED: NO DOCKET #  
 FACIL: 50-315 Donald C. Cook Nuclear Power Plant, Unit 1, Indiana & 05000315  
 50-316 Donald C. Cook Nuclear Power Plant, Unit 2, Indiana & 05000316

AUTH. NAME AUTHOR AFFILIATION  
 HERING, R.F. Indiana & Michigan Electric Co.  
 RECIP. NAME RECIPIENT AFFILIATION  
 DENTON, H.R. Office of Nuclear Reactor Regulation, Director

SUBJECT: Responds to 820405 request for info re. inservice insp. program. Thirty-day extension required to respond to specific info requests due to need for reinsp, re-evaluation & consultation w/inservice insp contractor.

DISTRIBUTION CODE: A047S COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 1  
 TITLE: Inservice Inspection/Testing & Related Correspondence

NOTES:

	RECIPIENT ID CODE/NAME		COPIES		RECIPIENT ID CODE/NAME		COPIES	
			LTR	ENCL			LTR	ENCL
	ORB #1 BC	01	7	7	NRR CHANEY, D		1	0
INTERNAL:	ELD/HDS3		1	0	NRR/DE/MEB	15	1	1
	NRR/DE/MTEB	14	1	1	<u>REG FILE</u>	04	1	1
	RGN3		1	1				
EXTERNAL:	ACRS	16	10	10	LPDR	03	2	2
	NRC PDR	02	1	1	NSIC	05	1	1
	NTIS		1	1				

The first part of the document discusses the importance of maintaining accurate records of all transactions. It emphasizes that every entry should be supported by a valid receipt or invoice. This ensures transparency and allows for easy verification of the data.

In the second section, the author outlines the various methods used to collect and analyze the data. This includes both primary and secondary data collection techniques. The analysis focuses on identifying trends and patterns within the dataset.

The third part of the report details the results of the study. It shows that there is a significant correlation between the variables being measured. These findings are supported by statistical analysis and are consistent with previous research in the field.

Finally, the document concludes with a series of recommendations for future research. It suggests that further studies should be conducted to explore the underlying causes of the observed trends. Additionally, it recommends that the current findings be applied to improve existing practices and policies.

In summary, this report provides a comprehensive overview of the research project. It covers the methodology, results, and conclusions, offering valuable insights into the subject matter. The findings are expected to contribute to the existing body of knowledge and inform future research efforts.

# INDIANA & MICHIGAN ELECTRIC COMPANY

P. O. BOX 18  
BOWLING GREEN STATION  
NEW YORK, N. Y. 10004

May 13, 1982  
AEP:NRC:00070E

Donald C. Cook Nuclear Plant Unit Nos. 1 & 2  
Docket Nos. 50-315 and 50-316  
License Nos. DPR-58 and DPR-74  
INSERVICE INSPECTION PROGRAM

Mr. Harold R. Denton, Director  
Office of Nuclear Reactor Regulation  
U.S. Nuclear Regulatory Commission  
Washington, D.C. 20555

Dear Mr. Denton:

The attachment to Mr. S. A. Varga's letter of April 5, 1982 contains a request for information relative to the Inservice Inspection (ISI) program for the Donald C. Cook Nuclear Plant Unit Nos. 1 and 2. The ISI non-destructive examination program for Class 2 welds for the Cook Plant was developed for us by General Physics Corp. more than three years ago. The criteria for determining the exemptions and code relief requests at that time are not readily available either at General Physics or at our facilities and it appears that this information will have to be re-established. In addition, some information requested requires re-inspection by Plant personnel, reevaluation and consultation with our ISI contractor (Southwest Research Institute), and substantial engineering review. For example, the systems that were previously exempted because of chemistry control, under IWC-1220 (c) will now have to be added to the program. Therefore, we need a thirty day extension to respond to the individual items in Mr. Varga's letter. At that time we will either supply the requested information, or submit a schedule for obtaining the detailed information. We will also be able to indicate areas in which our ISI program may be modified.

This document has been prepared following Corporate procedures which incorporate a reasonable set of controls to insure its accuracy and completeness prior to signature by the undersigned.

Very truly yours,



R. F. Hering  
Vice President

A047  
1/1

RFH/md  
cc:(attached)

8205180270 Q

1948

1949

1950

1951

1952

1953

1954

1955

1956

1957

1958

1959

1960

1961

1962

1963

1964

1965

1966

1967

1968

1969

1970

1971

1972

1973

1974

1975

1976

1977

1978

1979

1980

1981

1982

1983

1984

1985

1986

1987

1988

1989

1990

1991

1992

1993

1994

1995

1996

1997

1998

1999

2000

2001

2002

2003

2004

2005

2006

2007

2008

2009

2010

2011

2012

2013

2014

2015

2016

2017

2018

2019

2020

2021

2022

2023

2024

2025

Mr. Harold R. Denton

- 2 -

AEP:NRC:00070E

cc: John E. Dolan - Columbus  
R. S. Hunter  
R. W. Jurgensen  
W. G. Smith, Jr. - Bridgman  
R. C. Callen  
G. Charnoff  
Joe Williams, Jr.  
NRC Resident Inspector at Cook Plant - Bridgman

Faint, illegible text or markings in the upper right quadrant of the page.