

DMB

March 20, 1985

Docket No. 50-315
Docket No. 50-316

American Electric Power Service
Corporation
Indiana and Michigan Electric Company
ATTN: Mr. John E. Dolan
Vice Chairman
Engineering and Construction
1 Riverside Plaza
Columbus, OH 43216

Gentlemen:

Attached is a revision to Inspection Reports No. 50-315/84-23(DRP) and
50-316/84-25(DRP). You are requested to make the revision as described.

In accordance with 10 CFR 2.790(a), a copy of this letter and the attachments
will be placed in the NRC Public Document Room.

We will gladly discuss any questions you may have concerning this revision.

Sincerely,

W. D. Shafer, Chief
Reactor Projects Branch 2

Enclosure: Revision
to Inspection Reports
No. 50-315/84-23(DRP) and
50-316/84-25(DRP)

cc w/encl:
W. G. Smith, Jr., Plant Manager
DMB/Document Control Desk (RIDS)
Resident Inspector, RIII
Ronald Callen, Michigan
Public Service Commission
EIS Coordinator, USEPA
Region 5 Office

RIII
[Signature]
Wright/rr
03/20/85

RIII
[Signature]
Shafer

8503260265 850320
PDR ADDCK 05000315
Q PDR

IE01

1952

OFFICE OF THE DIRECTOR
BUREAU OF REVENUE
WASHINGTON, D. C.

RECEIVED
MAY 15 1952

1952

1952

1952

1952

Revision Sheet

Change

Add Section 7, Monthly Maintenance Observation.

Reason

Section 7, "Monthly Maintenance Observation", was accidentally omitted during processing of Report 315/84-23; 316/84-25.

Instructions

1. Place cover letter and revision sheet prior to page 1 of Inspection Reports 315/84-23(DRP) and 316/84-25(DRP).
2. Remove pages 10 and 11.
3. Add new pages 10, 11, and 12.



1953

1. The first part of the report deals with the general situation in the country.

2. The second part of the report deals with the economic situation in the country.

3. The third part of the report deals with the social situation in the country.

4. The fourth part of the report deals with the political situation in the country.

5. The fifth part of the report deals with the cultural situation in the country.

