

APR 1 1985

85-09

Docket No. 50-315  
Docket No. 50-316

American Electric Power Service  
Corporation  
Indiana and Michigan Electric Company  
ATTN: Mr. John E. Dolan  
Vice Chairman  
1 Riverside Plaza  
Columbus, OH 43216

Gentlemen:

This refers to the routine safety inspection conducted by Messrs. B. L. Jorgensen and J. K. Heller of this office on February 12, 1985 through March 18, 1985 of activities at the Donald C. Cook Nuclear Plant, Units 1 and 2 authorized by NRC Operating Licenses No. DPR-58 and DPR-74 and to the discussion of our findings with W. G. Smith, Jr., and others of your staff during the course of and at the conclusion of the inspection.


The enclosed copy of our inspection report identifies areas examined during the inspection. Within these areas, the inspection consisted of a selective examination of procedures and representative records, observations, and interviews with personnel.

No items of noncompliance with NRC requirements were identified during the course of this inspection.

In accordance with 10 CFR 2.790(a), a copy of this letter and the enclosure will be placed in the NRC Public Document Room.

8504110287 850401  
PDR ADOCK 05000315  
Q PDR

71  
IED1



American Electric Power Service  
Corporation

2

APR 1 1985

We will gladly discuss any questions you have concerning this inspection.

Sincerely,

"Original signed by W. D. Shafer"

W. D. Shafer, Chief  
Reactor Projects Branch 2

Enclosure: Inspection Reports  
No. 50-315/85009(DRP);  
No. 50-316/85009(DRP)

cc w/encl:  
W. G. Smith, Jr., Plant Manager  
DMB/Document Control Desk (RIDS)  
Resident Inspector, RIII  
Ronald Callen, Michigan  
Public Service Commission  
EIS Coordinator, USEPA  
Region 5 Office  
Nuclear Facilities and  
Environmental Monitoring  
Section

RIIV  
Stuehmann/rr  
03/30/85

RIII  
Wright

RIII  
Shafer

