

Dmb

AUG 22 1985

Docket No. 50-315/85-20
Docket No. 50-316

American Electric Power Service
Corporation
Indiana and Michigan Electric Company
ATTN: Mr. John E. Dolan
Vice Chairman
1 Riverside Plaza
Columbus, OH 43216

Gentlemen:

This refers to the routine safety inspection conducted by B. L. Jorgensen, J. K. Heller, C. L. Wolfsen, and L. E. Kanter of this office on June 25 through July 22, 1985, of activities at the Donald C. Cook Nuclear Plant, Units 1 and 2, authorized by NRC Operating Licenses No. DPR-58 and DPR-74 and to the discussion of our findings with W. G. Smith, Jr. and others of your staff during the course of and at the conclusion of the inspection.

The enclosed copy of our inspection report identifies areas examined during the inspection. Within these areas, the inspection consisted of a selective examination of procedures and representative records, observations, and interviews with personnel.

No violations of NRC requirements were identified during the course of this inspection.

In accordance with 10 CFR 2.790(a), a copy of this letter and the enclosure will be placed in the NRC's Public Document Room.

8508270181 850822
PDR ADOCK 05000315
Q PDR

JE01

1948

1948

American Electric Power
Service Corporation

2

AUG 22 1985

We will gladly discuss any questions you have concerning this inspection.

Sincerely,

N. J. Chrissotimos, Chief
Reactor Projects Branch 2

Enclosure:

Inspection Reports

No. 50-315/85020(DRP);

No. 50-316/85020(DRP)

cc w/enclosure:

W. G. Smith, Jr., Plant Manager
DMB/Document Control Desk (RIDS)
Resident Inspector, RIII
Ronald Callen, Michigan
Public Service Commission
EIS Coordinator, USEPA
Region 5 Office
Nuclear Facilities and
Environmental Monitoring
Section

RIII

OK for
Kanter/Wolfsen/rr
08/09/85

RIII

JFS
Suermann
8/21

YES

RIII

Weil
Weil
8/21/85

RIII

Chrissotimos
Chrissotimos
8/21