

## NUCLEAR REGULATORY COMMISSION WASHINGTON D. C. 20555

DEC 3 1 1985

Docket Nos.: 50-315 and 50-316

> Mr. John Dolan, Vice President Indiana and Michigan Electric Company c/o American Electric Power Service Corporation 1 Riverside Plaza Columbus, Ohio 43216

Dear Mr. Dolan:

Subject: Supplement 1 to NUREG-0737, Request for Modification of Commission


Order Dated July 12, 1985

Re: Donald C. Cook Nuclear Plant, Unit Nos. 1 and 2

The July 12, 1985, Order, established December 1985 completion dates for the Safety Parameter Display Systems (SPDS), the Emergency Operating Procedures (EOPs), and the Emergency Response Facilities. The December 1985 date corresponded to the planned 1985 Unit 2 outage for fuel reload. The Order also established December 1986 as a completion date for the Detailed Control Room Design Review. By letter dated November 27, 1985, the Indiana and Michigan Electric Company requested a modification of the dates corresponding to the 1985 refueling outage and provided new completion dates for the SPDS, EOPs, and the Emergency Response Facilities.

In July and August 1985, the Unit 2 experienced three unplanned outages due to steam generator tube leaks. As a result of the steam generator repair outages, the refueling outage has been delayed until no later than February 28, 1986. The original completion date, December 1985, corresponded to 1 month after the original planned refueling outage. Therefore, the new proposed completion date based on the February 1986 refueling date is March 1986. The one completion date of December 1986 for the Detailed Control Room Design Review remains unchanged.

In your earlier submittals, you based the completion schedules for the SPDS, EOPs, and Emergency Response Facilities on the implementation of the EOPs in Unit Nos. 1 and 2 at the same time. The SPDS is included in the new EOPs and both are to be located in the Emergency Response Facilities. For Unit 1, the implementation of the EOPs and SPDS in March 1986 is appropriate; however, since the SPDS in Unit 2 will not be required before startup following the refueling outage, we agree that the SPDS completion date for Unit 2 (and operability) may correspond to the startup following the refueling. The Emergency Response Facilities which are shared by both units are to be complete in March 1986 with the exception that the Unit 2 SPDS be installed and operational as planned but at the startup following the Unit 2 refueling outage. A revised chart of the acceptable dates is enclosed.



Based on your submittals, which were addressed above, we find that you have shown good cause for the requested extensions; that the extensions are in response to staff concerns or were otherwise unavoidable; that the extensions appear reasonable; and that you have made a good faith effort to comply with the schedule contained in the Commission's Order of July 12, 1985. Therefore, in accordance with the terms of Section V of the July 12, 1985, Commission Order, we conclude that there is adequate justification for modification of the Commission's Order and, hereby, grant the requested extensions.

Sincerely,

Original signed by: Thombs M. Novak

Thomas M. Novak, Acting Director Division of PWR Licensing-A, NRR

Enclosure: Licensee's Additional

Comments on Supplement 1

to NUREG-0737

cc: See next page

DISTRIBUTION:

Docket File

NRC PDR

Local PDR

PRC System

PWR#4 Rdg

**MDuncan** 

DWigginton

OELD

ACRS (10)

JPartlow<sup>®</sup>

**EJordan** 

**BGrimes** 

PWR#4/DPWR-A
DWigginton/mac
12/3(/85

PWR#4/DPWR-A MQuackn /11/1 12/3//85 PWRY4/PPYR-A BJYdungbflood

0ELD KCyr

D/DPWR-A TMNovak

2/3/ /85

h j s<sup>3</sup> kg c 1<sub>1</sub>

## DONALD C: COOK NUCLEAR PLANT

## LICENSEE'S ADDITIONAL COMMITMENTS ON SUPPLEMENT 1 TO NUREG-0737

	TITLE		REQUIREMENTS	LICENSEE'S COMPLETION SCHEDULE (OR STATUS)
1.	Safety Parameter Display System (SPDS)	1b.	SPDS fully operational and operators trained	March 1986*
2.	Detailed Control Room Design Review (DCRDR)	2b.	Submit a summary report to the NRC including a proposed schedule for implementation.	December 1986
4.	Upgrade Emergency Operating Procedures (EOPs)	4b.	Implement the upgraded EOPs	March 1986
5.	Emergency Response Facilities Fully Functional	5a. 5b. 5c.		Complete* Complete Complete*

<sup>\*</sup> SPDS to be installed and operational March 1986 for Unit 1 and at the startup following the 1986 refueling outage for Unit 2.

Mr. John Dolan Indiana and Michigan Electric Company

cc:
Mr. M. P. Alexich
Vice President
Nuclear Operations
American Electric Power Service
Corporation
1 Riverside Plaza
Columbus, Ohio 43215

Attorney General Department of Attorney General 525 West Ottawa Street Lansing, Michigan 48913

Township Supervisor Lake Township Hall Post Office Box 818 Bridgman, Michigan 49106

W. G. Smith, Jr., Plant Manager Donald C. Cook Nuclear Plant Post Office Box 458 Bridgman, Michigan 49106

U.S. Nuclear Regulatory Commission Resident Inspectors Office 7700 Red Arrow Highway Stevensville, Michigan 49127

Gerald Charnoff, Esquire Shaw, Pittman, Potts and Trowbridge 1800 M Street, N.W. Washington, DC 20036

Mayor, City of Bridgeman Post Office Box 366 Bridgman, Michigan 49106

Special Assistant to the Governor Room 1 - State Capitol Lansing, Michigan 48909

Nuclear Facilities and Environmental Monitoring Section Office Division of Radiological Health Department of Public Health 3500 N. Logan Street Post Office Box 30035 Lansing, Michigan 48909 Donald C. Cook Nuclear Plant

The Honorable John E. Grotberg United States House of Representatives Washington, DC 20515

Regional Administrator, Region III U.S. Nuclear Regulatory Commission 799 Roosevelt Road Glen Ellyn, Illinois 60137

J. Feinstein
American Electric Power
Service Corporation
1 Riverside Plaza
Columbus, Ohio 43216