NUCLEAR REGULATORY COMMISSION

REGION III

Reports No. 50-315/86018(DRSS); 50-316/86018(DRSS)

Docket Nos. 50-315; 50-316 Licenses No. DPR-58; DPR-74

Licensee: American Electric Power Service Corporation

Indiana and Michigan Electric Company

1 Riverside Plaza Columbus, OH 43216

Facility Name: Donald C. Cook Nuclear Power Station, Units 1 and 2

Inspection At: Donald C. Cook Site, Bridgman, MI

Inspection Conducted: April 14-18, 1986

Date of Last Physical Protection Inspection: February 24-27, 1986

Type of Inspection: Announced, Reactive Physical Security Inspection

Inspectors:

J. K Kniceley for T. J. Madeda

Physical Security Inspector

Safequards Group IV

Physical Security Inspector

5/1/26

J. R. Kniceley

Physical Security Inspector

Approved By:

J/. R. Creed, Chief

Safeguards Section

Inspection Summary

Inspection on April 14-18, 1986 (Reports No. 50-315/86018(DRSS); 50-316/86018 (DRSS))

Areas Inspected: Included a review of security management effectiveness; security organization; records and reports; testing and maintenance; locks, keys and combinations; physical barrier - vital areas; power supply;

8605050210 860501 PDR ADDCK 05000315

Enclosure contains SAFEGUARDS INFORMATION Upon separation this page is Decontrolled

enistano mas loni ITIMO Enistration Allo sul antenes de loni Solle sunocentralista locationes de locations

lighting; compensatory measures; access control - personnel, packages and vehicles; detection aids - vital areas; alarm stations; personnel training and qualifications; contingency plan review and safeguards information. The inspection began during the dayshift.

Results: The licensee was found to be in compliance with NRC requirements in the areas inspected. Two open items were identified during this inspection.

All previously identified violations and open items were closed.

Enclosure contains SAFEGUARDS INFORMATION Upon separation this page is Decontrolled

And the Books of the state of t

١