## DEC 4 1986

Docket No. 50-315 Docket No. 50-316

American Electric Power Service
Corporation
Indiana and Michigan Electric Company
ATTN: Mr. John E. Dolan
Vice Chairman
Engineering and Construction
1 Riverside Plaza
Columbus, OH 43216

## Gentlemen:

This refers to the routine safety inspection conducted by B. L. Jorgensen and J. K. Heller of this office on September 9 through November 3, 1986, of activities at the Donald C. Cook Nuclear Plant, Units 1 and 2 authorized by NRC Operating Licenses No. DPR-58 and No. DPR-74 and to the discussion of our findings with W. G. Smith, Jr., and others of your staff during the course of and at the conclusion of the inspection.

The enclosed copy of our inspection report identifies areas examined during the inspection. Within these areas, the inspection consisted of a selective examination of procedures and representative records, observations, and interviews with personnel.

No violations of NRC requirements were identified during the course of this inspection.

In accordance with 10 CFR 2.790 of the Commission's regulations, a copy of this letter, and the enclosed inspection report will be placed in the NRC Public Document Room.

We will gladly discuss any questions you have concerning this inspection.

Sincerely,

Originial Signed by W. G. Guldemond W. G. Guldemond, Chief Projects Branch 2

Enclosure: Inspection Reports
No. 50-315/86035(DRP);

No. 50-316/86035(DRP)

See Attached Distribution

Burgess/nma

RIII.

Guldemond 124184

RIII

RIII Weil 12/3/82

Paragraph 9.d Allegation

Closure

8612100104 861204 PDR ADOCK 05000315 Q PDR ZEU1

1/1

2

American Electric Power Service Corporation

## Distribution

cc w/enclosure:
W. G. Smith, Jr., Plant Manager
DCS/RSB (RIDS)
Licensing Fee Management Branch
Resident Inspector, RIII
Ronald Callen, Michigan
Public Service Commission
EIS Coordinator, USEPA
Region 5 Office
Nuclear Facilities and
Environmental Monitoring
Section

