

## REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 8707100342 DOC. DATE: 87/06/30 NOTARIZED: NO DOCKET #  
 FACIL: 50-315 Donald C. Cook Nuclear Power Plant, Unit 1, Indiana & 05000315  
 50-316 Donald C. Cook Nuclear Power Plant, Unit 2, Indiana & 05000316  
 AUTH. NAME AUTHOR AFFILIATION  
 SAUER, W. D. Region 3, Office of Director  
 RECIP. NAME RECIPIENT AFFILIATION  
 DOLAN, J. E. Indiana & Michigan Electric Co.

SUBJECT: Forwards Insp Repts 50-315/87-13 & 50-316/87-13 on 870519-22  
 & 870601-02. No violations noted.

DISTRIBUTION CODE: IE06D COPIES RECEIVED: LTR 1 ENCL 1 SIZE: 2+9  
 TITLE: Environ & Radiological (50 DKT)-Insp Rept/Notice of Violation Respons

## NOTES:

RECIPIENT ID CODE/NAME	COPIES LTTR ENCL	RECIPIENT ID CODE/NAME	COPIES LTTR ENCL
PD3-3 LA	1 0	PD3-3 PD	1 1
WIGGINGTON, D	1 1		
INTERNAL: AEOD/DOA	1 1	AEOD/DSP	1 1
NMSS/SOGB	1 1	NRR/DOEA/EAB	1 1
NRR/DREP/EPB	1 1	NRR/DREP/RPB	2 2
NRR/PMAS/ILRB	1 1	OGC/HDS1	1 1
REG FILE 02	1 1	RES	1 1
RES DEPY GI	1 1	RGN3 FILE 01	1 1
RGN2/DRSS/EPRPB	1 1	RGN4 MURRAY, B	1 1
EXTERNAL: LPDR	1 1	NRC PDR	1 1
NSIC	1 1		

JUN 30 1987

Docket No. 50-315  
Docket No. 50-316

American Electric Power Service  
Corporation  
Indiana and Michigan Electric Company  
ATTN: Mr. John E. Dolan  
Vice Chairman  
Engineering and Construction  
1 Riverside Plaza  
Columbus, OH 43216

Gentlemen:

This refers to the routine safety inspection conducted by Mr. L. J. Hueter of this office on May 19-22 and June 1-2, 1987, of activities at D. C. Cook Nuclear Plant, Units 1 and 2 authorized by NRC Operating Licenses No. DPR-58 and No. DPR-74 and to the discussion of our findings with Mr. L. S. Gibson at the conclusion of the inspection and a followup discussion with Mr. T. A. Kriesel and other members of your staff by telephone on June 9, 1987.

The enclosed copy of our inspection report identifies areas examined during the inspection. Within these areas, the inspection consisted of a selective examination of procedures and representative records, observations, and interviews with personnel.

No violations of NRC requirements were identified during the course of this inspection.

In accordance with 10 CFR 2.790 of the Commission's regulations, a copy of this letter and the enclosed inspection report will be placed in the NRC Public Document Room.

We will gladly discuss any questions you have concerning this inspection.

Sincerely,

"Original signed by W. Snell"

W. D. Shafer, Chief  
Emergency Preparedness and  
Radiological Protection Branch

8707100342 870630  
PDR ADDCK 05000315  
PDR  
Q

Enclosure: Inspection Reports  
No. 50-315/87013(DRSS);  
No. 50-316/87013(DRSS)

See Attached Distribution

RIII  
LJH  
Hueter/jaw

RIII  
MS  
Schumacher  
6/25/87

RIII  
BIB  
Burgess  
6/29/87

RIII  
WDS  
Shafer  
6/30/87

TE 06  
11

American Electric Power Service  
Corporation

2 JUN 30 1987

Distribution

cc w/enclosure:

W. G. Smith, Jr., Plant Manager

DCS/RSB (RIDS)

Licensing Fee Management Branch

Resident Inspector, RIII

Ronald Callen, Michigan

Public Service Commission

EIS Coordinator, USEPA

Region V Office

Nuclear Facilities and

Environmental Monitoring

Section