REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

DOCKET # DOC. DATE: 87/09/28 NOTARIZED: NO ACCESSION NBR: 8710020263 FACIL; 50-315 Donald C. Cook Nuclear Power Plant, Unit 1, Indiana & 05000315 50-316 Donald C. Cook Nuclear Power Plant, Unit 2, Indiana & 05000316

AUTHOR AFFILIATION AUTH, NAME ARRISON, J. J.

Region 3, Office of Director

RECIP. NAME

RECIPIENT AFFILIATION

DOLAN, J. E.

American Electric Power Co., Inc.

DOLAN, J. E.

Indiana & Michigan Electric Co.

SUBJECT: Forwards Insp Repts 50-315/87-16 & 50-316/87-16 on

870707-17 & 0915 & notice of violation.

DISTRIBUTION CODE: 1E01D COPIES RECEIVED: LTR _ ENCL _ SIZE: 2+28 TITLE: General (50 Dkt)-Insp Rept/Notice of Violation Response

NOTES:

	RECIPIENT ID CODE/NAME PD3-3 PD	COPIES LTTR ENCL 1 1	RECIPIENT ID CODE/NAME WIGGINGTON, D	COPIES LTTR ENCL 2 2
INTERNAL:	AEOD NRR MORISSEAU, D NRR/DREP/EPB NRR/DRIS DIR DE LIEBERMAN, J REG_EILE RGN3 FILE 01	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	DEDRO NRR/DOEA DIR NRR/DREP/RPB NRR/PMAS/ILRB OGC/HDS1 RES DEPY GI	1 1 1 2 2 1 1 1 1 1 1 1 1 1 1
ERNAL:	LPDR NSIC	1 1 1 1	NRC PDR	1 1

SEP 28 1987

Docket No. 50-315 Docket No. 50-316

American Electric Power Service
Corporation
Indiana and Michigan Electric Company
ATTN: Mr. John E. Dolan
Vice Chairman
Engineering and Construction
1 Riverside Plaza
Columbus, OH 43216

Gentlemen:

This refers to the special safety inspection conducted by Messrs. Tony Fresco, Jeff Holmes, and Joseph Ulie of this office on July 7-17 and September 15, 1987, of activities at the D. C. Cook Nuclear Plant, Units 1 and 2, authorized by NRC Operating Licenses No. DPR-58 and No. DPR-74, and to the discussion of our findings with Mr. Wilbur G. Smith and others of your staff at the conclusion of the inspection.

The enclosed copy of our inspection report identifies areas examined during the inspection. Within these areas, the inspection consisted of a selective examination of procedures and representative records, observations, and interviews with personnel.

During this inspection, certain of your activities appeared to be in violation of NRC requirements, as described in the enclosed Notice. The inspection showed that action had been taken to correct the identified violations and to prevent recurrence. Our understanding of your corrective actions are described in Paragraphs 2.r and 2.s of the enclosed inspection report. Consequently, no reply to the violations is required, and we have no further questions regarding these matters at this time. In addition, based on my inspectors review, it appears that further management attention is needed to resolve certain emergency remote shutdown and associated repair procedures discrepancies.

In accordance with 10 CFR 2.790 of the Commission's regulations, a copy of this letter and the enclosed inspection report will be placed in the NRC Public Document Room.



1/1 /E01

P

We will gladly discuss any questions you have concerning this inspection.

Sincerely,

Criginal Signed by L. L. Harrison

J. J. Harrison, Chief Engineering Branch

Enclosures:

-1. Notice of Violation

2. Inspection Reports

No. 50-315/87016(DRS); No. 50-316/87016(DRS)

cc w/enclosures:
W. G. Smith, Jr., Plant
 Manager
DCS/RSB (RIDS)

Licensing Fee Management
Branch

Resident Inspector, RIII
Ronald Callen, Michigan
Public Service Commission
EIS Coordinator, USEPA
Region V Office
Nuclear Facilities and
Environmental Monitoring
Section

RIII Plie/abl 9/27/87 RIII AH Holmes 9/18/87

RIII RNN Gardner 1/28/17 RIII Burgess 9/2487 RIII Grobe 12187

RNING Harrison 9/28/87