## REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR: 8712110230 DOC. DATE: 87/12/02 NOTARIZED: NO DOCKET # FACIL: 50-315 Donald C. Cook Nuclear Power Plant, Unit 1, Indiana & 05000315 50-316 Donald C. Cook Nuclear Power Plant, Unit 2, Indiana & 05000316

AUTH. NAME AUTHOR AFFILIATION

SHAFER, W. D. Region 3, Ofc of the Director

RECIP. NAME RECIPIENT AFFILIATION

DOLAN, J. E. Indiana Michigan Power Co. (formerly Indiana & Michigan Ele

SUBJECT: Forwards Safefty Insp Repts 50-315/87-30 & 50-316/87-30 on

871103-06. No violations noted.

DISTRIBUTION CODE: 1E06D COPIES RECEIVED: LTR  $\frac{1}{2}$  ENCL  $\frac{1}{2}$  SIZE:  $\frac{2+8}{2}$  TITLE: Environ & Radiological (50 DKT)-Insp Rept/Notice of Violation Respons

## NOTES:

RECIPIENT COPIES RECIPIENT ID CODE/NAME LTTR ENCL ID CODE/NAME PD3-3 LA 1 0 PD3-3 PD WIGGINGTON, D 1 1	COPIES E LTTR ENCL 1 1
INTERNAL: AEOD/DOA 1 1 AEOD/DSP	1 1
NMSS/LLOB 1 1 NMSS/SGOB	1 1
NRR/DLPG/PEB 1 1 NRR/DOEA/EAB	1 1
NRR/DREP/EPB 1 1 NRR/DREP/RPB	2 2
NRR-/PMAS/ILRB 1 1 OGC/HDS1	· 1 1
REG FILE 02 1 1 RES	1 1
RES DEPY GI 1 1 RGN3 FILE C	1 1 1
RGN2/DRSS/EPRPB 1 1 RGN4 MURRAY, B	<b>i i</b>
TERNAL: LPDR 1 1 NRC PDR	1 1
NSIC 1 1	

Docket No. 50-315 Docket No. 50-316

Indiana Michigan Power Company ATTN: Mr. John E. Dolan Vice Chairman Engineering and Construction 1 Riverside Plaza Columbus, OH 43216

## Gentlemen:

This refers to the routine safety inspection conducted by Messrs. Januska and Bocanegra of this office on November 3-6, 1987, of activities at D. C. Cook Nuclear Plant, Units 1 and 2, authorized by NRC Operating Licenses No. DPR-58 and No. DPR-74 and to the discussion of our findings with Mr. W. Smith, Jr. and others of your staff at the conclusion of the inspection. Additional discussions were held with K. Haglund on November 12 and 13, 1987.

The enclosed copy of our inspection report identifies areas examined during the inspection. Within these areas, the inspection consisted of a selective examination of procedures and representative records, observations, and interviews with personnel. In addition, our Mobile Laboratory was at the site during the inspection to perform independent measurements of radioactivity.

No violations of NRC requirements were identified during the course of this inspection.

In accordance with 10 CFR 2.790 of the Commission's regulations, a copy of this letter and the enclosed inspection report will be placed in the NRC Public Document Room.

We will gladly discuss any questions you have concerning this inspection.

moriginal signed by W.D. Shafer"

8712110230 871202 PDR ADOCK 05000315

W. D. Shafer, Chief Emergency Preparedness and Radiological Protection Branch

Enclosure: Inspection Reports No. 50-315/87030(DRSS); No. 50-316/87030(DRSS)

See Attached Distribution

RIII

(AS)

Januska/crr

Bocanegra

R(III -Dia ys Schumacher RIII Kur for Burgess (2/187 RIII |Share

TE04

## <u>Distribution</u>

cc w/enclosure:
W. G. Smith, Jr., Plant Manager
DCD/DCB (RIDS)
Licensing Fee Management Branch
Resident Inspector, RIII
Ronald Callen, Michigan
Public Service Commission
EIS Coordinator, USEPA
Region 5 Office
Michigan Department of
Public Health